



PHOTOGRAPH LOG
Mingus Area

Project Name: USFS Preliminary Assessment/Site Inspection (PA/SI)	Site Location: Prescott National Forest, Yavapai County, Arizona	Project No. 12767.204.001
---	--	-------------------------------------

Photo No. 1	Date: 3/9/2015
------------------------------	--------------------------

Direction Photo Taken: Northeast
--

Description: Background soil sample location MBG-S1.
--





Photo No. 2	Date: 3/9/2015
------------------------------	--------------------------

Direction Photo Taken: Southeast
--

Description: Background soil sample location MBG-S2.
--





PHOTOGRAPH LOG
Mingus Area

Project Name: USFS Preliminary Assessment/Site Inspection (PA/SI)	Site Location: Prescott National Forest, Yavapai County, Arizona	Project No. 12767.204.001
---	--	-------------------------------------

Photo No. 3	Date: 3/9/2015
------------------------------	--------------------------

Direction Photo Taken: South
--

Description:
Background soil sample location MBG-S3.





Photo No. 4	Date: 3/9/2015
------------------------------	--------------------------

Direction Photo Taken: Southeast
--

Description:
Background soil sample location MBG-S4.





PHOTOGRAPH LOG
Mingus Area

Project Name:

USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:

Prescott National Forest, Yavapai County, Arizona

Project No.

12767.204.001

Photo No.
5

Date:
3/9/2015

Direction Photo Taken:

North

Description:

Background soil sample location MBG-S5.




Photo No.
6


Date:
3/9/2015

Direction Photo Taken:

North

Description:

Background soil sample location MBG-S6. Area 1 is visible in the background.





PHOTOGRAPH LOG
Mingus Area

Project Name: USFS Preliminary Assessment/Site Inspection (PA/SI)	Site Location: Prescott National Forest, Yavapai County, Arizona	Project No. 12767.204.001
---	--	-------------------------------------

Photo No. 7	Date: 3/9/2015
Direction Photo Taken: Northeast	

Description:
Background sediment sample location MBG-Sed1, marked by the shovel



Photo No. 8	Date: 3/9/2015
Direction Photo Taken: Northeast	

Description:
Background sediment sample location MBG-Sed2, marked by the shovel.





PHOTOGRAPH LOG
Mingus Area

Project Name: USFS Preliminary Assessment/Site Inspection (PA/SI)	Site Location: Prescott National Forest, Yavapai County, Arizona	Project No. 12767.204.001
---	--	-------------------------------------

Photo No. 9	Date: 3/9/2015
------------------------------	--------------------------

Direction Photo Taken: North
--

Description:
Background sediment sample location MBG-Sed3, marked by the shovel.



Photo No. 10	Date: 3/9/2015
-------------------------------	--------------------------

Direction Photo Taken: North
--

Description:
Background sediment sample location MBG-Sed4, marked by the shovel.





PHOTOGRAPH LOG
Mingus Area

Project Name: USFS Preliminary Assessment/Site Inspection (PA/SI)	Site Location: Prescott National Forest, Yavapai County, Arizona	Project No. 12767.204.001
---	--	-------------------------------------

Photo No. 11	Date: 3/10/2015
-------------------------------	---------------------------

Direction Photo Taken:
North

Description:
Sediment sample location MBO-Sed1, located in Blowout Creek, adjacent to Area 2 and upstream of Area 3.



Photo No. 12	Date: 3/10/2015
-------------------------------	---------------------------

Direction Photo Taken:
Southwest

Description:
Sediment sample location MBO-Sed2, located in Blowout Creek, adjacent to Areas 2 and 3.





PHOTOGRAPH LOG
Mingus Area

Project Name: USFS Preliminary Assessment/Site Inspection (PA/SI)	Site Location: Prescott National Forest, Yavapai County, Arizona	Project No. 12767.204.001
---	--	-------------------------------------

Photo No. 13	Date: 3/10/2015
-------------------------------	---------------------------

Direction Photo Taken:
East

Description:
Sediment sample location MBO-Sed3, located in Blowout Creek, downstream of Area 3.



Photo No. 14	Date: 3/10/2015
-------------------------------	---------------------------

Direction Photo Taken:
West

Description:
Sediment sample location MBO-Sed4, located in Blowout Creek, downstream of sediment sample location MBO-Sed3.





PHOTOGRAPH LOG
Mingus Area

Project Name: USFS Preliminary Assessment/Site Inspection (PA/SI)	Site Location: Prescott National Forest, Yavapai County, Arizona	Project No. 12767.204.001
---	--	-------------------------------------

Photo No. 15	Date: 3/10/2015
-------------------------------	---------------------------

Direction Photo Taken: North
--

Description:
Sediment sample location MUN-Sed5, located in the unnamed wash, adjacent to Area 1.



Photo No. 16	Date: 3/10/2015
-------------------------------	---------------------------

Direction Photo Taken: Northeast
--

Description:
Sediment sample location MUN-Sed6, located in the unnamed wash, downstream of Area 1.





PHOTOGRAPH LOG
Mingus Area

Project Name:
USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:
Prescott National Forest, Yavapai County, Arizona

Project No.
12767.204.001

Photo No.
17

Date:
3/10/2015

Direction Photo Taken:

Northeast

Description:

Sediment sample location MUN-Sed7, located in the smaller drainage, downstream of Area 1.



Photo No.
18

Date:
3/10/2015

Direction Photo Taken:

Southwest

Description:

Sediment sample location MUN-Sed8, located in the unnamed wash, downstream of MUN-Sed7.





PHOTOGRAPH LOG
Mingus Area

Project Name:
USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:
Prescott National Forest, Yavapai County, Arizona

Project No.
12767.204.001

Photo No.
19

Date:
3/9/2015

Direction Photo Taken:

South

Description:

Excavation at MA1-ES1, Area 1.



Photo No.
20

Date:
3/9/2015

Direction Photo Taken:

West

Description:

The west wall of MA1-ES1, Area 1. Refusal (bedrock) was reached at 4 feet bgs; only samples MA1-ES1-1 and MA1-ES1-3 collected. No trash/debris was observed in the excavation.





PHOTOGRAPH LOG
Mingus Area

Project Name:
USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:
Prescott National Forest, Yavapai County, Arizona

Project No.
12767.204.001

Photo No.
21

Date:
3/9/2015

Direction Photo Taken:

South

Description:

The south wall of MA1-ES2, Area 1. No surface trash observed other than shooting debris; no trash observed down to 1 foot bgs.

Excavator hit refusal at 1 foot bgs. No samples collected at 3 and 5 feet bgs.



Photo No.
22

Date:
3/9/2015

Direction Photo Taken:

North

Description:

Excavation at MA1-ES3, Area 1. Different bottles and other trash, as well as a tank, are observed in the pothole.



Project Name:

USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:

Prescott National Forest, Yavapai County, Arizona

Project No.

12767.204.001

Photo No.
23

Date:
3/9/2015

Direction Photo Taken:

Northeast

Description:

Bottles and tires excavated from MA1-ES3.

Tires were removed from the Site by the USFS and disposed at the local landfill.



Photo No.
24

Date:
3/9/2015

Direction Photo Taken:

South

Description:

Water heater excavated from MA1-ES3. Water heater was removed from the Site by the USFS and disposed at the local landfill.





PHOTOGRAPH LOG
Mingus Area

Project Name:

USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:

Prescott National Forest, Yavapai County, Arizona

Project No.

12767.204.001

Photo No.
25

Date:
3/9/2015

Direction Photo Taken:

West

Description:

The west wall of MA1-ES3, Area 1. Wood enclosure with metal protruding from center visible in the upper right portion of the photograph.



Photo No.
26

Date:
3/9/2015

Direction Photo Taken:

East

Description:

A large pile of trash/debris excavated at sample location MA1-ES4, Area 1. Trash/debris included bottles, plastic bags, tires and cardboard.





PHOTOGRAPH LOG
Mingus Area

Project Name:

USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:

Prescott National Forest, Yavapai County, Arizona

Project No.

12767.204.001

Photo No.
27

Date:
3/9/2015

Direction Photo Taken:

North

Description:

Debris excavated from MA1-ES4, including glass bottles and plastic bags.



Photo No.
28

Date:
3/9/2015

Direction Photo Taken:

East

Description:

The east wall of MA1-ES5, Area 1. Heavy trash/debris is visible in the test pothole and to the right of the photo. Trash/debris included various glass and plastic bottles and plastic bags.





PHOTOGRAPH LOG
Mingus Area

Project Name:
USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:
Prescott National Forest, Yavapai County, Arizona

Project No.
12767.204.001

Photo No.
29

Date:
3/9/2015

Direction Photo Taken:

North

Description:

The north wall of MA1-ES5, Area 1. Several tires were recovered.



Tires

Photo No.
30

Date:
3/10/2015

Direction Photo Taken:

North

Description:

The north wall of MA1-ES6, Area 1. Layer of trash/debris is visible at a depth of 3.5 to 4 feet in the north wall of the test pothole and may extend further beyond the pothole. Trash/debris included assorted glass and plastic bottles, tires, and general household trash.



Layer of trash/debris



PHOTOGRAPH LOG
Mingus Area

Project Name: USFS Preliminary Assessment/Site Inspection (PA/SI)	Site Location: Prescott National Forest, Yavapai County, Arizona	Project No. 12767.204.001
---	--	-------------------------------------

Photo No. 31	Date: 3/9/2015
-------------------------------	--------------------------

Direction Photo Taken:
South

Description:
South wall of MA1-ES7, Area 1. Only a single metal can be observed in this excavation.



Photo No. 32	Date: 3/10/2015
-------------------------------	---------------------------

Direction Photo Taken:
Downward

Description:
Looking into the excavated sample location MA1-ES8, Area 1. Several pieces of scrap metal are visible in the center of the test pothole at 5 feet bgs.





PHOTOGRAPH LOG
Mingus Area

Project Name:
USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:
Prescott National Forest, Yavapai County, Arizona

Project No.
12767.204.001

Photo No.
33

Date:
3/9/2015

Direction Photo Taken:

East

Description:

Excavated pieces of scrap metal from sample location MA1-ES9, Area 1.



Photo No.
34

Date:
3/9/2015

Direction Photo Taken:

South

Description:

Looking south at excavated sample location MA1-ES10, Area 1. Moderate trash/debris is visible in the test pothole and at the excavated pile to the right.





PHOTOGRAPH LOG
Mingus Area

Project Name:
USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:
Prescott National Forest, Yavapai County, Arizona

Project No.
12767.204.001

Photo No.
35 **Date:**
3/10/2015

Direction Photo Taken:
East


Description:
Looking east at excavated sample location MA1-ES11, Area 1. Minimal to no trash/debris excavated at this location.



Photo No.
36 **Date:**
3/13/2015

Direction Photo Taken:
Southeast

Description:
Area 1, soil sample location MA1-S1, with soil sample locations MA1-S18 and MA1-S19 in the background.





PHOTOGRAPH LOG
Mingus Area

Project Name:

USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:

Prescott National Forest, Yavapai County, Arizona

Project No.

12767.204.001

Photo No.

37

Date:

3/13/2015

Direction Photo Taken:

East

Description:

Area 1, soil sample location MA1-S2, with soil sample location MA1-S3 in the background.




Photo No.

38

Date:


3/13/2015

Direction Photo Taken:

Northeast

Description:

Area 1, soil sample location MA1-S4, with soil sample location MA1-S5 in the background.





PHOTOGRAPH LOG
Mingus Area

Project Name:
USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:
Prescott National Forest, Yavapai County, Arizona

Project No.
12767.204.001

Photo No.
39

Date:
3/13/2015

Direction Photo Taken:

Northeast

Description:

Area 1, soil sample location MA1-S6, with soil sample location MA1-S7 in the background.

MA1-S7 is located just beyond the service road.



Photo No.
40


Date:
3/13/2015

Direction Photo Taken:

North

Description:

Area 1, soil sample location MA1-S7 with Area 3 in the background.





PHOTOGRAPH LOG
Mingus Area

Project Name:
USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:
Prescott National Forest, Yavapai County, Arizona

Project No.
12767.204.001

Photo No.
41

Date:
3/12/2015

Direction Photo Taken:

Northeast

Description:

Area 1, soil sample location MA1-S8.



Photo No.
42


Date:
3/12/2015

Direction Photo Taken:

South

Description:

Area 1, soil sample location MA1-S9.





PHOTOGRAPH LOG
Mingus Area

Project Name: USFS Preliminary Assessment/Site Inspection (PA/SI)	Site Location: Prescott National Forest, Yavapai County, Arizona	Project No. 12767.204.001
---	--	-------------------------------------

Photo No. 43	Date: 3/12/2015
Direction Photo Taken: East	
Description: Area 1, soil sample location MA1-S10.	





Photo No. 44	Date: 3/12/2015
Direction Photo Taken: West	
Description: Area 1, soil sample location MA1-S11, with soil sample location MA1-S4 in the background.	





PHOTOGRAPH LOG
Mingus Area

Project Name:
USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:
Prescott National Forest, Yavapai County, Arizona

Project No.
12767.204.001

Photo No.
45 **Date:**
3/12/2015

Direction Photo Taken:
South

Description:
Area 1, soil sample location MA1-S12, with soil sample location MA1-S21 in the background.





Photo No.
46 **Date:**
3/12/2015

Direction Photo Taken:
East

Description:
Area 1, soil sample location MA1-S13, with soil sample location MA1-S23 in the background.





PHOTOGRAPH LOG
Mingus Area

Project Name:
USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:
Prescott National Forest, Yavapai County, Arizona

Project No.
12767.204.001

Photo No.
47 **Date:**
3/12/2015

Direction Photo Taken:
East

Description:
Area 1, soil sample location MA1-S14, with soil sample location MA1-S23 in the background.



Photo No.
48 **Date:**
3/13/2015

Direction Photo Taken:
South

Description:
Area 1, soil sample location MA1-S15.





PHOTOGRAPH LOG
Mingus Area

Project Name:
USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:
Prescott National Forest, Yavapai County, Arizona

Project No.
12767.204.001

Photo No.
49

Date:
3/12/2015

Direction Photo Taken:

Northeast

Description:

Area 1, soil sample location MA1-S16, with soil sample location MA1-S17 in the background.




Photo No.
50

Date:
3/12/2015

Direction Photo Taken:

South

Description:

Area 1, soil sample location MA1-S20, with soil sample location MA1-S19 in the background.





PHOTOGRAPH LOG
Mingus Area

Project Name:

USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:

Prescott National Forest, Yavapai County, Arizona

Project No.

12767.204.001

Photo No.
51

Date:
3/12/2015

Direction Photo Taken:

Northeast

Description:

Area 1, soil sample location MA1-S22, with soil sample location MA1-S23 in the background.




Photo No.
52


Date:
3/12/2015

Direction Photo Taken:

North

Description:

Area 1, soil sample location MA1-S27, with soil sample location MA1-S24 in the background.





PHOTOGRAPH LOG
Mingus Area

Project Name:
USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:
Prescott National Forest, Yavapai County, Arizona

Project No.
12767.204.001

Photo No.
53

Date:
3/13/2015

Direction Photo Taken:

South

Description:

Area 1, soil sample location MA1-S25, with soil sample location MA1-S28 in the background.




Photo No.
54


Date:
3/12/2015

Direction Photo Taken:

Southwest

Description:

Area 1, soil sample location MA1-S26, with soil sample location MA1-S4 in the background.





PHOTOGRAPH LOG
Mingus Area

Project Name:
USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:
Prescott National Forest, Yavapai County, Arizona

Project No.
12767.205.001

Photo No.
55

Date:
3/13/2015

Direction Photo Taken:

South

Description:

Area 1, soil sample location MA1-S29.




Photo No.
56


Date:
3/12/2015

Direction Photo Taken:

North

Description:

Area 1, soil sample location MA1-S30.





PHOTOGRAPH LOG
Mingus Area

Project Name:

USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:

Prescott National Forest, Yavapai County, Arizona

Project No.

12767.205.001

Photo No.
57

Date:
3/10/2015

Direction Photo Taken:

South

Description:

Looking south at excavated sample location MA2-ES1, Area 2. Minimal to no trash/debris present.

Crew hit refusal at 3 feet bgs due to the amount of rocks in the area.



Photo No.
58

Date:
3/10/2015

Direction Photo Taken:

East

Description:

Looking at the east wall of excavated sample location MA2-ES2, Area 2. Moderate to high amount of trash/debris excavated, including sheet metal and other various scrap metal, wood, various glass bottles and a hot water tank.





PHOTOGRAPH LOG
Mingus Area

Project Name:

USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:

Prescott National Forest, Yavapai County, Arizona

Project No.

12767.205.001

Photo No.
59

Date:
3/10/2015

Direction Photo Taken:

Downward

Description:

Various glass jars recovered from MA2-ES2, Area 2. These items were removed from the Site by the USFS OSC and taken to a USFS archaeologist for dating.



Photo No.
60

Date:
3/10/2015


Direction Photo Taken:

Down

Description:

Various glass jars recovered from MA2-ES2, Area 2.

The item in the center appears to be a corroded piece of copper.





PHOTOGRAPH LOG
Mingus Area

Project Name:
USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:
Prescott National Forest, Yavapai County, Arizona

Project No.
12767.205.001

Photo No.
61

Date:
3/10/2015

Direction Photo Taken:

Downward

Description:

Hot water tank excavated at location MA2-ES2, Area 2.



Photo No.
62

Date:
3/10/2015

Direction Photo Taken:

South

Description:

Looking at the south wall of excavated sample location MA2-ES3, Area 2. Low to moderate amount of trash/debris excavated, including sheet metal, pipes and various small jars.





PHOTOGRAPH LOG
Mingus Area

Project Name:
USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:
Prescott National Forest, Yavapai County, Arizona

Project No.
12767.205.001

Photo No.
63

Date:
3/10/2015

Direction Photo Taken:

Downward

Description:

White powdery material recovered from MA2-ES3, Area 2.



Photo No.
64

Date:
3/10/2015

Direction Photo Taken:

South

Description:

Scrap metal recovered from excavated sample location MA2-ES4, Area 2.





PHOTOGRAPH LOG
Mingus Area

Project Name:
USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:
Prescott National Forest, Yavapai County, Arizona

Project No.
12767.205.001

Photo No.
65

Date:
3/10/2015

Direction Photo Taken:

West

Description:

Various small glass bottles recovered from excavated sample location MA2-ES4, Area 2.



Photo No.
66

Date:
3/10/2015

Direction Photo Taken:

South

Description:

Looking south at excavated sample location MA2-ES5, Area 2. No trash/debris present.

Crew hit refusal at 4 feet bgs due to the amount of rocks in the area.





PHOTOGRAPH LOG
Mingus Area

Project Name:
USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:
Prescott National Forest, Yavapai County, Arizona

Project No.
12767.205.001

Photo No.
67

Date:
3/11/2015

Direction Photo Taken:

South

Description:

Excavator working on sample location MA2-ES6, Area 2. No trash/debris present.

A soil gas marker from a previous investigation is located near the excavation.



Photo No.
68

Date:
3/11/2015

Direction Photo Taken:

West

Description:

Looking west at excavated sample location MA3-ES1, Area 3. No trash/debris present.





PHOTOGRAPH LOG
Mingus Area

Project Name:
USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:
Prescott National Forest, Yavapai County, Arizona

Project No.
12767.205.001

Photo No.
69

Date:
3/11/2015

Direction Photo Taken:

Down

Description:

Plastic bags recovered at excavated sample location MA3-ES2, Area 3.



Photo No.
70

Date:
3/11/2015

Direction Photo Taken:

East

Description:

Looking east at excavated sample location MA3-ES3, Area 3. No trash/debris present.





PHOTOGRAPH LOG
Mingus Area

Project Name:
USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:
Prescott National Forest, Yavapai County, Arizona

Project No.
12767.205.001

Photo No.
71

Date:
3/11/2015

Direction Photo Taken:

North

Description:

Looking north at excavated sample location MA3-ES4, Area 3. No trash/debris present.



Photo No.
72

Date:
3/12/2015


Direction Photo Taken:

Northeast

Description:

Area 3, soil sample location MA3-S1.

The windsock located in Area 3 is in the background.





PHOTOGRAPH LOG
Mingus Area

Project Name:
USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:
Prescott National Forest, Yavapai County, Arizona

Project No.
12767.205.001

Photo No.
73

Date:
3/12/2015

Direction Photo Taken:

East

Description:

Area 3, soil sample location MA3-S2.

The entrance gate to Area 3 is in the background to the right.




Photo No.
74


Date:
3/12/2015

Direction Photo Taken:

South

Description:

Area 3, soil sample location MA3-S3.





PHOTOGRAPH LOG
Mingus Area

Project Name:
USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:
Prescott National Forest, Yavapai County, Arizona

Project No.
12767.205.001

Photo No.
75

Date:
3/12/2015

Direction Photo Taken:

Description:

Area 3, soil sample location MA3-S4.

The windsock located in Area 3 is in the background.



Photo No.
76

Date:
3/12/2015


Direction Photo Taken:

West

Description:

Area 3, soil sample location MA3-S5.

The windsock located in Area 3 is in the background.





PHOTOGRAPH LOG
Mingus Area

Project Name:
USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:
Prescott National Forest, Yavapai County, Arizona

Project No.
12767.205.001

Photo No.
77 **Date:**
3/12/2015

Direction Photo Taken:
West

Description:
Area 3, soil sample location MA3-S6.

The windsock located in Area 3 is in the background.





Photo No.
78 **Date:**
3/12/2015

Direction Photo Taken:

Description:
Area 3, soil sample location MA3-S7, with soil sample location MA3-S10.





PHOTOGRAPH LOG
Mingus Area

Project Name:
USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:
Prescott National Forest, Yavapai County, Arizona

Project No.
12767.205.001

Photo No.
79

Date:
3/12/2015

Direction Photo Taken:

Southwest

Description:

Area 3, soil sample location MA3-S9, with soil sample locations MA3-S18 and MA3-S11 in the background.




Photo No.
80

Date:
3/12/2015


Direction Photo Taken:

North

Description:

Area 3, soil sample location MA3-S11.

The windsock located in Area 3 is in the background.





PHOTOGRAPH LOG
Mingus Area

Project Name:

USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:

Prescott National Forest, Yavapai County, Arizona

Project No.

12767.204.001

Photo No.
81

Date:
3/12/2015

Direction Photo Taken:

South

Description:

Area 3 overview, with MA3-ES3 pictured in the foreground post excavation and refill.



Photo No.
82

Date:
3/13/2015

Direction Photo Taken:

East

Description:

Area 1 overview, with MA1-ES3 pictured in the foreground post excavation and refill.





PHOTOGRAPH LOG
Mingus Area

Project Name:

USFS Preliminary Assessment/Site Inspection (PA/SI)

Site Location:

Prescott National Forest, Yavapai County, Arizona

Project No.

12767.204.001

Photo No.
83

Date:
3/13/2015

Direction Photo Taken:

North

Description:

Area 2 overview, with MA2-ES4 pictured in the foreground post excavation and refill.

