

## **APPENDIX B**

---

**IMAGES FROM THE GEOMORPHIC RECONNAISSANCE OF THE  
TALLAC AND SPRING CREEK WATERSHED**



B1. Mouth of Tallac Creek showing slightly incised channel and eroding banks



B2. Tallac Creek at the sewer line – this line acts as a grade control structure

Source: PWA 2003

## Images from the Geomorphic Reconnaissance of the Tallac and Spring Creek Watershed

Appendix B



B3. Convergence of the Tallac Creek distributary channels in the lower wetland



B4. Western-most distributary channel of Tallac Creek

Source: PWA 2003

## Images from the Geomorphic Reconnaissance of the Tallac and Spring Creek Watershed

Appendix **B**



B5. The main channel in the lower Tallac wetland



B6. Main channel of Tallac Creek in the wetland area

Source: PWA 2003

## Images from the Geomorphic Reconnaissance of the Tallac and Spring Creek Watershed

Appendix B



B7. High flow channel in Tallac Creek wetland



B8. Disorganized drainage and wetland in the lower beaver dam area of Tallac Creek wetland

Source: PWA 2003

## Images from the Geomorphic Reconnaissance of the Tallac and Spring Creek Watershed

Appendix B



B9. The large beaver dam area of Tallac Creek wetland



B10. Steeper riffle-pool channel in Tallac Creek between the beaver dams and SR 89

Source: PWA 2003

## Images from the Geomorphic Reconnaissance of the Tallac and Spring Creek Watershed

Appendix **B**



B11. Tallac Creek above SR 89



B12. Tallac Creek above the confluence with Spring Creek

Source: PWA 2003

## Images from the Geomorphic Reconnaissance of the Tallac and Spring Creek Watershed

Appendix B



B13. Tallac Creek obliterated by debris flow material and vegetation



B14. Tallac Creek below the Spring Creek Rd culvert, showing debris flow deposits

Source: PWA 2003

## Images from the Geomorphic Reconnaissance of the Tallac and Spring Creek Watershed

Appendix B



B15. Culvert at Spring Creek Rd showing debris flow deposits



B16. Channel filled in with debris flow deposits above the Spring Creek Rd culvert

Source: PWA 2003



B17. Tallac Creek above the debris flow deposits – step-pool channel



B18. Eroding outside bend in scoured reach alongside Spring Creek Rd (staff is 16 ft)

Source: PWA 2003

## Images from the Geomorphic Reconnaissance of the Tallac and Spring Creek Watershed

Appendix B



B19. Headwater tributary of Tallac Creek above Spring Creek Rd



B20. Spring Creek above the confluence with Tallac Creek


Source: PWA 2003

## Images from the Geomorphic Reconnaissance of the Tallac and Spring Creek Watershed

Appendix B



B21. Mid way up Spring Creek



B22. Spring Creek in the upper meadow

Source: PWA 2003

## Images from the Geomorphic Reconnaissance of the Tallac and Spring Creek Watershed

Appendix B