

Holloway Lake Dam Monitoring
July 1, 2010

Bill Goslin

This information was collected on a brief visit to the dam during inspection of the trail clearing contract. This is a photo of the main dam. The reservoir was at full pool. There was no observed seepage in the dam. The headgate was closed. It has been several years since the last maintenance work at the dam. Everything looked OK.



This photo is of an auxiliary dam a short distance to the north. No seepage here. The area appeared free from litter, construction materials or tool caches. Driftwood is usually not a problem at Holloway. The water level was normal so the spill way was not checked because of time constraints.

