


Detail: Existing Condition



Existing Condition:

- Drained lake bed with incised channels
- High Hazard Dam remains

