APPENDIX C -- ROAD TREATMENT AND FUTURE THINNING RECOMMENDATIONS

Road conditions, problems, and plantation acres by Forest Road. Plantations with patchy or low stocking density are not expected to require thinning within the next 20 years. Road closures are as directed in Forestwide Access & Travel Management (ATM) Plan.

Forest Road Number	Plantation acres ready for thinning in next 1-5 years, stocking density, and silviculture priority	Plantation acres ready for Thinning in 5-20 years or low stocking	Waterbars previously placed or needed now & road closure recommendations	Culvert Problems Identified in Roads Assessment	Road Topo-graphic Position
2400	184 ac - densely stocked, high priority 18 ac - densely stocked, medium priority	182 ac-≈ year 2010	ATM Road --primary use/maintenance	Fish passage problem (48") on Carter Cr. at MP 10.8 5 partially plugged culverts need maintenance	2/3 Mid-slope, 1/3 Ridgetop
2400-888	None	1 medium priority unit in Lower Siuslaw watershed. 12 acres patchy stocking			3/4 Ridgetop, 1/4 midsl.
2400-889	None	Partial access to patchy stocking unit on spur -888	Recommend waterbar and close	None	Midslope
2400-950	47 ac densely stocked, medium priority	151 ac ≈ year 2020	Recommend waterbar	None	2/3 Ridge 1/3 Midsl
2400-951	None	Partial access to unit on spur road 950	Recommend waterbar and close	None	Midslope
2400-952	15 ac - densely stocked, high priority	None	Previously waterbarred	None	Midslope
2400-949	Partial access above unit	Partial access to above 14 ac unit	Not previously waterbarred	None	Ridgetop
2400-937	None	Partial access to above unit	Recommend waterbar and close	None	midslope
2400-948	81 ac - densely stocked, high priority	20 ac patchy, low stocking	Recommend waterbars (will use road in 5 yrs.)	None	1/2 Ridgetop

	21 ac - densely stocked mediu priority				1/2 Midslope
2400-944	17 ac - densely stocked, medium priority	Partial access to 90 ac unit above	Previously waterbarred	None	Ridgetop
2400-953 Canary Road	None	3 units in Lower Siuslaw watershed	Previously waterbarred	3 partially plugged culverts at MP 1.0. Access from Canary Rd.	Predom. Ridgetop
2490 Henderson Tie Rd.	70 ac - densely stocked, high priority 143 ac - densely stocked, medium priority	Possible second thinning on Henderson units. 55 ac patchy and low stocking	None	3 partially plugged culverts. One completely plugged culvert with water diversion potential at MP 1.14	Midslope
2490-947 Henderson Spur	88 ac - densely stocked, high priority 58 ac densely stocked, medium priority	10 ac ≈ year 2010 100 ac low stocking	Previously waterbarred	2 partially plugged culverts on spur 947. Water diversion potential at MP 0.7	Midslope
2490-946 Henderson Spur	31 ac - densely stocked, high priority 25 ac - densely stocked, medium priority	30 ac ≈ year 2023 40 acres low priority and priority	Previously waterbarred Close for wildlife	3 partially plugged culverts on spur 946	Midslope
2480 Sunset Road	79 ac - densely stocked, high priority	149 ac ≈ year 2020 40 ac low priority and stocking	ATM Road --secondary use/ maintenance	None	1/2 Midsl. 1/2 Ridge
2480-935	None	101 ac ≈ year 2025	Recommend waterbar and close. Close for wildlife		3/4 Ridge 1/4 Midsl
2480-938	None	77 ac ≈ year 2010 Partial access to 2025 unit	Recommend waterbar *7 ac PROGENY SITE*	1 partially plugged culvert with water diversion potential	Ridgetop
2480-939?	None	1 unit ≈ year 2010	Previously waterbarred	None	Midslope
Road 4830 Mt. Popo Road	50 ac - densely stocked, high priority 203 ac - densely stocked, medium priority	41 ac ≈ year 2020 210 ac patchy stocking, low priority	ATM Road	None	Ridgetop

4830-958	143 ac - densely stocked, high priority 40 ac - densely stocked, medium priority	100 ac ≈ year 2010 120 ac ≈ year 2010 (although patchy) 65 ac low priority	Recommend waterbar Close for wildlife	None	Ridgetop
4830-961	None	15 ac ≈ year 2010 Partial access to large unit about year 2020	Recommend waterbar and close	None	Ridgetop
4830-962	None	60 ac ≈ year 2010	Recommend waterbar and close. Close for wildlife	None	Ridgetop
4830-963	None	50 ac ≈ year 2010	Recommend waterbar and close. Close for wildlife	None	Midslope
4830-964	None	Shares units with Spur 963	Recommend waterbar and close. Close for wildlife	1 culvert partially plugged with water diversion potential	Ridgetop
4830-965 (Private Access to Fiddle Cr.)	None (Use Spur-958)	22 ac ≈ year 2010	Recommend waterbar upper road segment	None	Ridgetop on USFS
4830-967	None	20 ac ≈ year 2020	Recommend waterbar and close. Close for wildlife	None	Ridgetop
4830-968	Shares densely stocked, medium priority unit with Road 4830	None	Recommend waterbar	None	Ridgetop
4830-969	Shares densely stocked, medium priority unit with Road 4830	132 ac ≈ year 2010	Recommend waterbar	None	Ridgetop
4830-970	Shares densely stocked, high priority unit with Road 4830	35 ac ≈ year 2010	Recommend waterbar	None	Ridgetop
4830-971	None	44 ac ≈ year 2010 52 ac patchy, low priority units	Recommend waterbar and close. Close for wildlife	None	Ridgetop
4830-972	None	118 ac ≈ year 2010	Recommend waterbar and close with Spur 971 Close for wildlife	None	Ridgetop

4830-975	Shares densely stocked, medium priority unit with Road 4830	None	Recommend waterbar	None	Ridgetop
4830-977	None	106 ac ≈ year 2010	Recommend waterbar and close. Close for wildlife	None	Ridgetop
4830-980	38 ac densely stocked, medium priority unit	18 ac ≈ year 2010 25 ac ≈ year 2020	Recommend waterbar Close for wildlife	None	Midslope
Unnamed spur off 4830-980	None	56 ac ≈ year 2010	Recommend waterbar	None	Midslope
4830-981	Shares densely stocked, medium priority unit with Spu 980	134 ac ≈ year 2010	Recommend waterbar	2 partially plugged culverts One has unspecified proble	Midslope
4830-979	None	Partial access to a unit 2010	Close lower road after treating Spur -980 Close for wildlife	None	Midslope
4830-978	None	Partial access to a unit about year 2010	Recommend waterbar and close	None	Ridgetop Midslope
4830-982	None	179 ac ≈ year 2010	Recommend waterbar and close. Close for wildlife	None	Ridgetop
4830-983	None	13 ac ≈ year 2010.	Recommend waterbar and close with Spur 982	None	Ridgetop
4830-984	None	Partial access to one of the units off spur 982	Recommend waterbar and close with Spur 982 Close for wildlife	None	Ridgetop
4830-990 ?	None	39 acres ≈ year 2025 (Sugar Maple)	Recommend waterbar and close	None	Ridgetop
Rd 4811	114 ac densely stocked, high priority 37 ac densely stocked, medium priority	50 ac ≈ year 2010 189 ac ≈ year 2015 117 ac patchy or low priority	ATM Secondary-High Clearance	1 partially plugged culvert at MP 3.09 with water diversion potential	Ridgetop
4811-957	None	46 ac ≈ year 2010	Recommend waterbar and close	1 partially plugged culvert with water diversion	Midslope

				potential. 1 culvert with problem (not specified)	
4811-956?	None	20 ac ≈ year 2010 102 ac patchy stocking	Recommend waterbar and close	1 culvert with problem (unspecified) and water diversion potential.	Midslope
4811-036	51 ac - densely stocked, high priority unit 23 ac densely stocked, medium priority unit	45 ac low priority, patchy stocking may thin after year 2010	Previously waterbarred	None	Ridgetop
4811-038	Shares densely stocked, high priority unit with -036 spur	None	Previously waterbarred	None	Ridgetop
4811-039?	None	None	Previously waterbarred	None	Ridgetop
4811-040	None	73 ac ≈ year 2010 17 ac ≈ year 2020	Previously waterbarred	None	Ridgetop
4811-041	None	20 ac ≈ year 2010	Previously waterbarred Recommend close Close for wildlife	None	Ridgetop
Unnamed spur off 4811-036	None	110 ac ≈ year 2010	Recommend waterbar and close Close for wildlife	None	Ridgetop
4811-042	Shares densely stocked, medium priority unit with Rd 4811	Partial access to above 110 ac unit. 12 ac patchy stocking possible thin after 2010	Previously waterbarred	None	Ridgetop
4811-044	None	None	Recommend waterbar and close	None	Ridgetop
4811-011	None	Possibly one unit about year 2010 (low stocking)	Previously waterbarred	One culvert problem (not specified)	Ridgetop
Unnamed spur off 4811-011	None	None	Recommend waterbar and close	None	Midslope
Road 4900	none	30 ac ≈ year 2015			Midslope

FS portion		27 ac patchy, low stocking			here
4900-057	None	143 ac ≈ year 2010	Recommend waterbar lower 1/3 of the road	6 partially plugged culverts (?)	Ridgetop
4900-056	None	Shares units with Spur 4900-057	Recommend waterbar and close	None	Ridgetop
4900-063	63 ac - densely stocked, medium priority unit	62 ac ≈ year 2015	Recommend waterbar	May be private road	Midslope
4900-059		20 ac dense lodgepole pine ≈ year 2010			Mostly Ridgetop
4900-060	None	Partial access to above unit	Waterbar USFS road segment	None	Ridgetop