# W.F. Illinois River Watershed Analysis Update

June
2004

As a result of the Biscuit Fire 2002, conditions have changed since the 1997 W.F. Illinois River Watershed Analysis was completed. This document tiers to the 1997 W.F. Illinois River Watershed Analysis and updates the sections that have changed as a result of the fire.

Updated Sections include:

Aquatics
Wildlife
Vegetation
Insect
Transportation
POC

M. Mchugh- Geology
C. Park – Hydrology
D. Delany - Fish
R.Miller – Wildlife
N. Vagle - Vegetation
D. Goheen - Insect
C. Kaping – Transportation
F. Betlejewski - POC

# Aquatics

## Changes in Current Conditions

| West Fork Illinois River Watershed Vegetation Changes [a] | | | | | | | |
|---|---|---|---|---|---|---|---|
| | | Changes in Vegetation in Biscuit Fire Area | | | | | |
| Total Acres | Acres Harvested since 1997 on Federal Lands | Vegetation Change Class[1] | | | | Channel Instability[2] | Fire Lines[3] |
| | | 1 | 2 | 3 | 4 | | |
| 76936 | | 1008 | 6195 | 11236 | 3561 | 5 miles | 51 |

[a] *As noted in the Biscuit Recovery DEIS and Biscuit Post-Fire Assessment*

1. Class 1: Very little burn or under burn
   Class 2: Majority of vegetation burned; needles retained
   Class 3: All vegetation burned; needles retained
   Class 4: All vegetation burned; no needles retained

2. Acres of channel showing streambank instability; identified from post-fire aerial photo review
3. Acres of dozer firelines constructed for Biscuit Fire suppression

Naturally occurring inner gorge and slump/earthflow landslides are the dominant sedimentation processes in the watershed. Gully and surface erosion is a minor component of sedimentation, but can be locally significant where surface water is concentrated. The area is underlain predominantly by peridotite and serpentinite bedrock, with diorite and granitic intrusions. Landforms have generally subdued uplands, and deeply incised drainage channels. Wherever the channel widens, a braided stream pattern develops, a result of the high natural sediment stream loads, and there are colluvial/alluvial deposits that have subsequently been cut by stream erosion. Several small to moderate, shallow debris slides and ravelly soils can be seen on aerial photo investigation. Wildfire can affect slope stability through a loss of root strength, which plays a key role in contributing cohesion to shallow soils. Aerial photo and field reviews were conducted as part of the Biscuit Assessment. The extent of the Biscuit wildland fire made aerial photo interpretation of landforms much easier than those usually done under forested conditions. Approximately 19 acres of active landslides were mapped in Rough and Ready Creek from post-fire aerial photos outside of the Kalmiopsis Wilderness.

Channels showing streambank instability were also identified and mapped for the Assessment. Whether channel instability demonstrates a change in watershed conditions since 1997 is difficult to determine since these features are difficult to see under riparian canopy. However, the Biscuit assessment offered an opportunity to map channel instability so that future changes can be tracked on subsequent photo reviews. A very cursory review of active channel instability was

done to help identify areas that would be most susceptible to surface ravel and sloughing, and shallow debris failures, thus increasing potential for delivery of sediment to streams. In the West Fork watershed, several steams are significantly affected by roads, trails, and off road vehicle use, making it difficult to differentiate between naturally and road-related channel instability. Much of the riparian vegetation in both the north and south forks of Rough and Ready Creek was consumed by the wildland fire. There appears to be a greater degree of stream aggradation in the South Fork Rough and Ready Creeks, possibly resulting from increased ravel after the wildfire. Again, sediment in the channel that may appear to be freshly deposited may instead be older material now freshly disturbed by OHV traffic.

Ridges, hill slopes and stream terraces show active vehicle use from mining and recreation. The slopes and ridges are criss-crossed by numerous 4-wheel drive roads and OHV trails that have been made more obvious, and more susceptible to erosion and sedimentation by the effects of the Biscuit Fire. Approximately 51 acres of fireline and almost a dozen safety and/or staging areas were built using bulldozers for fire suppression during the Fire, much of them on serpentine soils. Serpentine soils are fine-grained, prone to gully erosion, and slow to revegetate. OHV use can accelerate or expand the erosion process. Although it is difficult to date trail use from aerial photo review, it appeared that several recent-appearing OHV and motorcycle trails now descend from firelines into drainage channels.

The 1997 Watershed Analysis gave several recommendations that are especially relevant for soils and geology as a result of the Biscuit Fire.

1. Research use of serpentine rock types for road aggregate, considering quality and durability, mineralogy, and potential to increase water turbidity.
    a. Salvage logging after the fire will require additional aggregate surfacing on haul roads.
2. Use soils and geology to help botanists evaluate rare plant distribution, and inventory potential of nickel laterite deposits.
    a. The fire opened and made more obvious areas with potential for mining and recreation. Identification of sensitive sites would before disturbance would offer more effective protection to rare plant populations.
3. Evaluate feasibility of revegetation of laterite mining pits.
    a. Older mining areas could be designated as disposal areas for material unsuitable for roads. There may be some management activities during timber salvage that would generate material (rock and soil) that could be used as topsoil for revegetation.

Specific road recommendations were not made in the Watershed Analysis, although restricting road access to limit the spread of POC root disease, botany and erosion was noted. The presence of dozer-constructed firelines will make this more imperative, as access and visibility has increased. Trails that switchback down steep slopes, and roads and trails that parallel or utilize stream channels should be the highest priority for consideration. Other than the McGrew trail that is discussed in both the Watershed Analysis and in the Biscuit Post-Fire Assessment, the system of spur roads off FSR 4402 should be evaluated, including roads 437, 443, 442, 444, and 449.

**Hydrology**

Water temperatures affect all aquatic biota and are a critical factor in maintaining and restoring healthy salmonid populations. The DEQ has established temperature criteria to protect temperature-sensitive, beneficial uses, including specific salmonid life cycle stages. The DEQ policy states "to protect aquatic ecosystems from adverse warming and cooling caused by

anthropogenic activities. The Commission intends to minimize the risk to cold-water aquatic ecosystems from anthropogenic warming, to encourage the restoration and protection of critical aquatic habitat, and to control extremes in temperature fluxuations due to anthropogenic activities. The Commission recognizes that some of the State's waters will, in their natural condition, not provide optimal thermal conditions at all places and at all times that salmonid use occurs. Therefore, it is especially important to minimize additional warming due to anthropogenic sources. In addition, the Commission acknowledges that control technologies, BMPs and other measures to reduce anthropogenic warming are evolving and that the implementation to meet these criteria will be an iterative process." (OAR Chapter 340, Division 41, pages 20-21.).

The DEQ rule states that unless superceded by the natural conditions criteria described in section (8) of this rule, or by subsequently adopted site-specific criteria approved by EPA, the temperature criteria for waters supporting salmonids are as follows (OAR Chapter 340, Division 41, page 21.):

> Salmon and steelhead spawning areas: 7-day-average maximum may not exceed 55.4 degrees F.
>
> Core cold water habitat: 7-day-average maximum may not exceed 60.8 degrees F.

Salmon and trout rearing and migration: 7-day-average maximum may not exceed 64.4 degrees F.

Fires, storms, and human activities such as timber harvest and road construction have the potential to influence temperature by reducing shade producing riparian vegetation or by changing the shape of the channel. Several streams in the fire area are listed as water quality limited because of elevated summer stream temperature. All of the listed streams have had their stream temperature influenced, to some degree, by all of the factors listed above. Following the fire it is estimated that 18% of the riparian canopy in the Pistol River Watershed was killed by the fire. No stream temperature monitoring data is available following the fire.

**Fish Habitat**

Species/Stocks Presence and Distribution: On 5/6/97, the National Marine Fisheries Service listed coho salmon as Threatened under the Endangered Species Act. On 5/5/99, they designated critical habitat to include all stream reaches accessible to coho salmon except areas above specific dams or longstanding, naturally impassible barriers. This definition of critical habitat greatly over estimates the occurrence of coho salmon because it ignores their reliance on abundant side-channel habitat. Streams occupied by coho salmon in the Rogue/South Coast basins typically have more than 10 percent side-channel habitat. Currently the Forest and NOAA Fisheries have agreed to use the StreamNet database (www.streamnet.org) to define critical habitat for coho salmon and Essential Fish Habitat (EFH) for coho and Chinook salmon.

Stream shade: The Biscuit Fire of 2002 burned through portions of both the Rough and Ready Creek and the Middle West Fork Illinois River subwatersheds and reduced stream shade along many stream reaches.

Large wood: Many riparian trees were killed by the Biscuit Fire and will become future sources of large wood to small tributary stream channels.

## Future Trends

### Geology/Soils

The inner gorge rock and debris slides will continue to ravel, slough, and fail in response to large storms and flood events.

A higher rate of surface (soil) erosion will occur until vegetation is reestablished, at least as shrubs and grass, in approximately 5 years. Slopes in the areas underlain by granitic or serpentinite rock types will revegetate more slowly, given the ravelly and droughty nature of those soils.

Roads and OHV trails that remain open, or do not have restrictions for soil conditions, time of use, and expansion limits will continue to erode. Those that impact channels will contribute to changes in channel morphology, decreased shade, and increased sedimentation.

### Fish Habitat

Stream shade: Stream shade will increase over time and, barring another fire, recover to pre-fire levels. The rate of recovery depends upon the site potential to grow shade producing plants and the stream width, as wider stream reaches require taller (older) trees for shade recovery.

Large wood and sediment: Large wood and sediment recruitment to stream channels tends to be episodic in nature. The amount, timing, and rate of large wood recruitment to stream channels are determined primarily by the disturbance interval. Streams affected by the Biscuit Fire will be receive relatively high inputs of large wood and sediment as dead and dying tress are recruited to stream channels through natural processes including slump failures and landslides. The rate of large wood recruitment is expected to be high initially and to gradually increase over the first six to seven years. It is at this point that tree root failure of killed trees is highest. Consequently, it coincides with the highest rate of slump failures and landslides. After this period, the rate of large wood and sediment recruitment is expected to slowly decrease over the next ten years to approximately pre-fire levels; followed by several decades, depending upon the disturbance interval, of lower than pre-fire levels.

## Management Opportunities

- There are numerous opportunities to restrict and/or decommission roads, especially those used by 4-wheel drive vehicles and OHV. For those trails designated for OHV use, reconstruction to accommodate drainage and erosion should be employed. Efforts should be made to limit the (possibly increasing) network of OHV and motorcycle roads and trails in the watershed.
- Stabilized and/or restore firelines and safety/staging areas in serpentine soils that may not have been repaired after the Biscuit Fire. Scarification and/or ripping, constructing drainage devices, seeding and planting in the area would move the area toward

restoration of productivity and reduce the erosion and sedimentation rates. Limit access to firelines.

- Riparian planting in areas of vegetation change 3 and 4, if those areas are not identified as having high fire return intervals; reforestation should move vegetation type toward appropriate Plant Association Group (PAG)
- Plant conifers along burned perennial stream reaches to improve future stream shade and large wood recruitment and retention. Give priority to areas with the following characteristics: relatively wide stream channels; good conifer site potential; south (shade producing) side of channel; total or nearly total conifer mortality; and at least 0.5 acre in size.

## References


West Fork Illinois River Watershed Analysis, Iteration 1.0, 1997, Siskiyou National Forest
Biscuit Post-Fire Assessment, 2003, Rogue River and Siskiyou National Forests
Draft Environmental Impact Statement, The Biscuit Fire Recovery Project, 2003. Rogue River and Siskiyou National Forests
Aerial Photo Review of 8/2003 1:40,000
Field reviews
USDA Forest Service, Siskiyou National Forest. Fisheries Report for the Biscuit Fire Recovery Project DEIS. 10/15/03
USDA Forest Service, Siskiyou National Forest. Biscuit Fire Assessment
USDA Forest Service, Siskiyou National Forest. Biological Assessment of Fire Suppression and Rehabilitation Activities. 11/12/02
USDA Forest Service, Siskiyou National Forest. Burned Area Emergency Rehabilitation

# Wildlife

## Introduction

The Biscuit Fire affected 29 % of this watershed. The Biscuit Post-fire Assessment (USDA 2003) and Biscuit Recovery EIS (USDA USDI 2003 and 2004) identified wildlife habitats that need protected and restored in the Biscuit Fire area in order to meet the Forest Service's desired conditions for wildlife; these needs are also relevant outside of the Biscuit Fire area. These habitats of concern are late-successional forest and the grass/forb element of savannas, forest under-stories, and meadows.

Late-successional forest habitats of concern include spotted owl nesting/roosting habitat and pine/deciduous oak woodland or savanna. Late-successional spotted owl nesting/roosting habitat is defined as dominated by trees > 21" dbh with moderate to high canopy cover, > 40 %, (Zabel et al. 2003). This nesting/roosting habitat includes mature (21-32" dbh) and old growth (>32" dbh) forest with canopy cover greater than 40%. Late-successional pine/deciduous oak habitat is defined as dominated by pine and deciduous oak trees > 21" dbh with low to moderate canopy cover with brush and grass/forb ground cover.

Fire and vegetation management affect these habitats of concern. The greatest potential for impacts to habitats of concern from fire is within fire regimes I and IIIA, and the greatest potential for impacts from vegetation management are from regeneration harvest or thinning.

The exclusion of low intensity fire and timber management practices has adversely affected habitats of concern in this watershed. Exclusion of low intensity fire reduced the amount of grass/forb habitats, because this allowed encroachment to increase forest canopy cover, which eliminates most grass/forb ground cover. In addition, exclusion of low intensity fire contributed to the massive mortality of forest habitats during the high-intensity burning of the Biscuit Fire; more late-successional forest was killed in fire regimes I and IIIA than in other, more mesic, fire regimes. Suppression of low intensity fire has increased the risk of losing late successional habitat to high intensity fire, and restoration of low intensity fire could reduce this potential, especially within fire regimes I and IIIA.

The effects from vegetation management to these habitats of concern are dependant upon treatment prescriptions. Treatments that help protect and restore habitats of concern are recommended, such as low intensity fire, while treatments that degrade or remove these habitats, such as harvest of large trees, are discouraged from a wildlife perspective.

Site Productivity

Late successional spotted owl habitat does not generally develop on serpentine sites with low or moderate productivity. This watershed contains about 41,400 acres of low or moderate productivity serpentine sites, which is 54 % of 76,900 acres in the watershed.

Fire Regime

Within the Biscuit Fire area (29 % of this watershed) 99 % is in fire regimes I or IIIA and 1 % in other fire regimes. This ratio is probably consistent across the entire watershed, because the remaining areas have similar environmental conditions.

## Changes in Current Conditions

Late-successional spotted owl habitat

The Biscuit Fire destroyed 11 % of mature and 6 % of the old growth spotted owl nesting/roosting habitat that existed before the fire in this watershed.

Currently, this watershed has 13 % mature and 11 % old growth on sites capable of developing late-successional spotted owl habitat. This amount of old growth is well below desired/historic levels.

Grass/forb habitats

The Biscuit Fire should have benefited grass/forb habitats where seed sources were present before the fire and where suppression rehab efforts included seeding.

## Future Trends

Forests will continue to be at risk from stand replacement fires, with areas in fire regime's I and IIIA having the highest risk. Suppression of low intensity fires will continue, which will result in continued encroachment of woody plants into deciduous oak savannas, meadows, and late-successional forest under-stories.

## Management Opportunities

Restoration of low intensity fires where they were historically common could help protect and restore habitats of concern within this watershed. Shaded fuel breaks or Fuels Management Zones (FMZs) could facilitate the restoration of low intensity fires, because they would provide relatively safe and defensible locations for managing fires at the landscape scale.

Previous ecosystem analyses at the watershed scale identified other relevant management opportunities; however, within fire regimes I and IIIA, there is probably no treatment more important than development and maintenance of FMZs, because these are needed in order to restore low intensity fire that helps protect and restore habitats of concern.

## References

1. Zabel, Cynthia J.; Jeffery R. Dunk, Howard B. Stauffer, Lynn M. Roberts, Barry S. Mulder, and Adrienne Wright. 2003. Northern spotted owl habitat models for research and management application in California (USA). Ecological

Applications. 13(4), 2003, pp. 1027-1040. Agee, J.K. 1993. Fire ecology of Pacific Northwest forests. Washington, D.C.: Island Press; 493 p.
2. USDA 2003. Biscuit Post Fire Assessment. Rogue River/Siskiyou National Forests.
3. USDA USDI 2003 and 2004. Rogue River/Siskiyou National Forest and Medford District BLM. Biscuit Recovery EIS: Draft and Final.

# Vegetation - Silviculture

## Changes in Current Conditions

In the summer of 2002, the Biscuit Fire burned 25,856 acres or 34% of the Watershed. The fire burned in a wide range of intensities and exhibited varying behavior. The effect on the forest vegetation is just as varied, ranging from nearly complete consumption of vegetation and woody material to light underburning with little effect on the dominant trees, creating a mosaic of dead and live vegetation. As noted in the Biscuit Fire Recovery Project DEIS, satellite imagery was used to create 4 classes of fire effects.

The codes in the Vegetation Change classification system are as follows:
1 = little or no change (majority of vegetation is alive, primarily low intensity under-burn);
2 = low change (majority of the vegetation is dead but some live trees remain; dead trees retain needles and leaves; primarily moderate to high intensity underburn);
3 = moderate change (all vegetation is dead but needles and leaves remain in the overstory; primarily from high intensity underburn);
4 = high change (trees are dead with few or no needles or leaves; primarily from crown fires).

The acreage results are displayed in Table 1, Vegetation Change for the Watershed.

| | Canopy Mortality Categories | | | | |
|---|---|---|---|---|---|
| | 1 (Little or no change) | 2 (Low) | 3 (Moderate) | 4 (High) | Fire Totals |
| Total Acres 76,938 | 4478 | 6506 | 11310 | 3563 | 25,856 |
| Percent of Area for Each Category | 17 | 25 | 44 | 14 | 100 |

The current condition of trees in the Biscuit Recovery Area contrasts starkly with the desired future condition projected in the Siskiyou National Forest Plan. The Forest Plan envisioned stands of late successional forest and plantations stocked with valuable conifers. The current reality in the Biscuit area is expanses of dead trees and sprouting brush, interspersed with under burned stands. Stands of varying age classes in commercial timber producing areas were set back to the earliest of age classes. Trees that shaded streams where salmonids thrive in the cool water are dead.
Areas of high severity burn are often far from conifer seed sources and within areas where significant hardwood and brush competition is expected. Natural regeneration of conifers is expected to require decades. Resprouting hardwood and brush are expected to dominate these sites for at least that period of time.
Some of the drier sites that were severely burned clearly manifest the consequences of over 50 years of effective fire exclusion. These south and west aspects were generally

open stands of large pine with some deciduous oak and little understory except grasses and forbs and occasional brush and small trees. In the past, these sites were maintained by a frequent, low intensity fire regime. By the time of the Biscuit Fire they had become choked with dense small trees and brush as a result of fire exclusion.

## Future Trends

Following the Fire, hardwood vegetation will sprout very rapidly in the tanoak PAGs. The growing space for conifers, that will seed in naturally or be planted, will be taken over by the aggressive sprouts. Many of the conifer trees that do become established, will grow very slowly or die due to lack of sunlight, moisture, or both. In the other PAGs, sprouting of hardwood vegetation is not expected to be as aggressive, and the natural and planted seedlings will have less competition.

## Management Opportunities

Many areas that burned with high severity supported stands of Port Orford-cedar, sugar pine, and western white pine, which were reduced by introduced diseases prior to the fire. Natural regeneration of these species is expected to be extremely low and without the planting of resistant stock their abundance may be significantly reduced over time.

Opportunities exist for salvage of dead trees for the next two to three years. After that, the wood will deteriorate and loose its value. Wood that is retained on site, will benefit the habitat of many species, if it does not burn in subsequent fires. In order to have large conifer trees in the future, planting and subsequent tending of the salvage sale plantations, existing plantations, riparian areas, oak-pine sites, and other planting will be necessary in many areas. Planting of disease resistant Port-Orford-cedar and sugar pine will be necessary in order to keep these two valuable species in the watershed.

## References

USDA Forest Service, Siskiyou National Forest. Biscuit Fire Assessment, 2003.
USDA Forest Service, Siskiyou National Forest. The Biscuit Fire Recovery Project, Draft Environmental Impact Statement, 2004.
Silvics of North America, Western white pine, p 385, Vol. 1-Conifers, Sugar Pine, p 375, and Port-Orford-cedar, p 94.

# Insect Considerations

## Changes in Current Conditions

Prior to occurrence of the Biscuit Fire, forest insects were not considered to constitute a significant concern in this watershed. The fire has changed this by killing or injuring substantial numbers of trees and predisposing them to possible insect attack.

## Future Trends

It is likely that insects will colonize fire-killed trees and infest and kill fire-injured trees within the burned areas in this watershed in the next few years. It is well documented that both bark beetles (family Scolytidae) and woodborers (families Cerambicidae, Buprestidae, Scolytidae, and Siricidae) readily infest trees injured but not killed outright by fire and that many species of woodborers infest fire-killed trees (Miller and Keen 1960, Furniss 1965, Furniss and Carolin 1977, Thomas and Agee 1986, Ryan 1990, Swezy and Agee 1990, Ryan and Frandsen 1991, Harrington and Sackett 1992, Flanagan 1996, Scott et al. 1996). In fact: a) most of the fire-injured trees that die in a burned area within the 5 years following a forest fire are infested by bark beetles, woodborers, or representatives of both groups concurrently, and b) insects along with decay fungi that they vector play significant roles in the deterioration of most fire killed trees.

A number of systems have been devised for risk rating the still-living trees in a burned area immediately after a fire and predicting which are most likely to succumb to subsequent bark beetle and woodborer infestation (Wagner 1961, Reinhart and Ryan 1988, Flanagan 1996, Southwest Oregon Forest Insect and Disease Service Center 2001, Scott et al 2002,). Use of the rating system devised by the Southwest Oregon Forest Insect and Disease Service Center on a sample of plots within the perimeter of the Biscuit Fire suggests that 40 percent of the fire-injured but still-living trees there are at high risk of bark beetle or woodborer infestation. This is also probably a reasonable estimate of the proportion of fire-injured trees in this watershed that are at high risk of infestation. In addition, there is a possibility that insect populations will build up sufficiently when fire-injured trees are infested to attack nearby uninjured trees.

## Management Opportunities

1) Trees killed outright by the fire could be removed before insects and decay fungi cause substantial deterioration. The sooner such trees are removed the less the likelihood of substantial amounts of deterioration. Rate of likely deterioration can be used in prioritizing treatments. Deterioration due to insects and associated fungi develops most quickly in smaller trees and thin-barked species though, given enough time, all fire-killed trees are eventually affected. Decisions on whether or not to salvage fire-killed trees should be made in the context of overall management objectives.

2) Fire injured but still living trees could be evaluated using a risk rating system, and high risk trees in strategic locations could be considered for treatment. Alternatively, fire injured trees could be monitored, and if significant numbers are infested, those in strategic locations could be considered for treatment. Treatment of high risk or insect infested trees would involve cutting and removal. If trees are removed quickly enough, this will reduce likelihood of insect spread to other trees. Decisions on whether or not to treat high-risk or recently-insect-infested trees should also be made in the context of overall management objectives.

## References


Flanigan, P. 1996.
Survival of fire-injured conifers. Fire Management Notes 56: 13-16.

Furniss, M.M. 1965.
Susceptibility of fire-injured Douglas-fir to bark beetle attack in southern Idaho. Journal of Forestry 63: 8-11.

Furniss, R.L. and V.M. Carolin. 1977.
Western forest insects. USDA Forest Service. Miscellaneous Publication No. 1339. 654 p.

Miller, J.M., and F.P. Keen. 1960.
Biology and control of the western pine beetle: a summary of the first fifty years of research. USDA Forest Service Miscellaneous Publication No. 800. 381 p.

Reinhart, E.D., and K.C. Ryan. 1988.
How to estimate tree mortality resulting from underburning. Fire Management Notes 49: 30-36.

Ryan, K. C. 1990.
Predicting prescribed fire effects on trees in the Interior West. In: M.E. Alexander, G.F. Bisgrove technical advisors. The art and science of fire management. Proceedings of the First Interior West Fire Council Annual Meeting. Forestry Canada, Northern Forestry Centre. P. 148-162.

Ryan, K.C., and W.H. Frandsen. 1991.
Basal injury from smoldering fires in mature *Pinus ponderosa* Laws. International Journal of Wildland Fire 1: 107-118.

Scott, D.W., C.L. Schmitt. And L. H. Spiegel. 2002.
Factors affecting survival of fire injured trees: a rating system for determining relative probability of survival of conifers in the Blue and Wallowa Mountains. USDA Forest Service. BMPMSC-03-01. 66p.

Scott. D.W., J. Szymoniak, and V. Rockwell. 1996.
Entomological concerns regarding burn characteristics and fire effects on tree species during prescribed landscape burns: burn severity guidelines and mitigation measures to minimize fire injuries. USDA Forest Service, Wallowa-Whitman National Forest. BMZ 97-1. 48 p.

Southwest Oregon Forest Insect and Disease Service Center. 2001.
Guidelines for selecting fire-injured trees that are likely to be infested by insects in Southwest Oregon forests. USDA Forest Service, Rogue River National Forest. 5 p.

Swezy, D.M., and J.K. Agee. 1990.
Prescribed fire effects on fine root and tree mortality in old-growth ponderosa pine. Canadian Journal of Forest Research 21:626-634.

Thomas, T.L. and J.K. Agee. 1986.
Prescribed fire effects on mixed conifer forest structure at Crater Lake, Oregon. Canadian Journal of Forest Research 16: 1082-1087.

Wagener, W.W. 1961.
Guidelines for estimating the survival of fire-damaged trees in California. USDA Forest Service, Pacific Southwest Forest and Range Experiment Station. Miscellaneous Paper 60. 11p.

# Transportation

## Changes in Current Conditions

The information provided in this update is generated from the Geographical Information System (GIS). This database provides spatial analytical information. Because this mileage is two-dimensional the actual field mileage will vary because of the terrain.

Forest Service policy is to maintain classified roads to their Road Maintenance Level as prescribed by the road management objective. The maintenance level defines the level of service provided by, and maintenance required for, a specific road, consistent with road management objectives and maintenance criteria. (FSH 7709.58, Sec 12.3 – Transportation System Maintenance Handbook)

**Maintenance Level 1:** Assigned to intermittent service roads during the time they are closed to vehicular traffic. The closure period must exceed 1 year. Basic custodial maintenance is performed to keep damage to adjacent resource to an acceptable level and to perpetuate the road to facilitate future management activities. Emphasis is normally given to maintaining drainage facilities and runoff patterns. Planned road deterioration may occur at this level. Appropriate traffic management strategies are "prohibit" and "eliminate". Roads receiving level 1 maintenance may be of any type, class or construction standard, and may be managed at any other maintenance level during the time they are open for traffic. However, while being maintained at level 1, they are closed to vehicular traffic, but may be open and suitable for non-motorized uses.

**Maintenance Level 2:** Assigned to roads open for use by high clearance vehicles. Passenger car traffic is not a consideration. Traffic is normally minor, usually consisting of one or a combination of administrative, permitted, dispersed recreation, or other specialized uses. Log haul may occur at this level. Appropriate traffic management strategies are either (1) discourage or prohibit passenger cars or (2) accept or discourage high clearance vehicles.

**Maintenance Level 3:** Assigned to roads open and maintained for travel by a prudent driver in a standard passenger car. User comfort and convenience are not considered priorities. Roads in this maintenance level are typically low speed, single lane with turnouts and spot surfacing. Some roads may be fully surfaced with either native or processed material. Appropriate traffic management strategies are either "encourage" or "accept." "Discourage" or "prohibit" strategies may be employed for certain classes of vehicles or users.

**Maintenance Level 4:** Assigned to roads that provide a moderate degree of user comfort and convenience at moderate travel speeds. Most roads are double lane and aggregate surfaced. However, some roads may be single lane. Some roads may be paved and/or dust abated. The most appropriate traffic management strategy is "encourage." However, the "prohibit" strategy may apply to specific classes of vehicles or users at certain times.

**Maintenance Level 5:** Assigned to roads that provide a high degree of user comfort and convenience. Normally, roads are double-lane, paved facilities. Some may be aggregate surfaced and dust abated. The appropriate traffic management strategy is "encourage."

In the Road Inventory there are currently:

- Maintenance Level 1 = 10.37 miles
- Maintenance Level 2 = 55.45 miles

- Maintenance Level 3 = 9.41 miles
- Maintenance Level 4 = 2.68 miles

The closed and decommissioned roads for West Fork Illinois River Watershed are listed below.

| | | |
|---|---|---|
| 1 - BASIC CUSTODIAL CARE (CLOSED) | 4400437 | 3.33 |
| | 4400438 | 2.34 |
| | 4400440 | 0.07 |
| | 4400441 | 0.30 |
| | 4400442 | 2.41 |
| | 4400446 | 0.16 |
| | 4400449 | 0.09 |
| | 4402031 | 0.50 |
| | 4803066 | 0.55 |
| | 4803078 | 0.21 |
| | 4803107 | 0.41 |
| 1 - BASIC CUSTODIAL CARE (CLOSED) Total | | 10.37 |

| | | | |
|---|---|---|---|
| DE - DECOMMISSIONED | 2 - HIGH CLEARANCE VEHICLES | 4803060 | 0.01 |
| | | 4803112 | 0.04 |
| | | 4402016 | 0.58 |
| | | 4402072 | 0.37 |
| | | 4402085 | 0.47 |
| | | 4402475 | 1.15 |
| | | 4402480 | 0.74 |
| | | 4803620 | 0.06 |
| DE - DECOMMISSIONED Total | | | 3.42 |

Due to the Biscuit fire and resulting lack of vegetation there is the potential for increased rain runoff in the Recovery Area. This runoff can cause erosion, gullies, and debris flows that could jeopardize roads, culverts, and bridges. Concentrated water and debris flow increases the risk of saturating and undermining road fill slopes, which can either slump or slide, narrow the road width, and cause increase in stream sediment. When a live stream culvert plugs, the water can wash out the road and divert the stream flow from the natural stream channel. Water diversions caused by plugged culverts can cause significant erosion damage and sediment delivery from both stream crossings and cross drainages, which continue to plug other culverts as they cascade down the road, creating deeper and wider erosion gullies.

Stream culverts are generally undersized to meet the 100-year storm event as per the Aquatic Conservation Strategy. These culverts are site specific. The transport of Port-Orford-cedar root disease is an additional concern when water tops roads.

During the initial (BAER) effort, both the Forest Service and BLM found many blocked culverts and slopes susceptible to mass erosion. Even though the fire was extensive, approximately 500,000 acres, this initial effort provided some partial road stabilization treatments on approximately 70 roads. These road treatments offered some initial runoff and storm relief for the first winter rains at those specific site locations. These road treatments were sporadic, and consisted of rolling dips over drainages; installing cross ditch drainages; outsloping road sections;

surface rock replacement; road maintenance activities such as ditch and culvert cleaning; culvert replacements; and slope reinforcement.

These stabilization treatments were successful in helping minimize the potential for road failures, and to decrease the accelerated sediment delivery to fish habitat and to downstream watersheds. However, after the first winter, there were washouts on roads; some of these were in controlled locations where stabilization techniques diverted the water back into its stream channel rather than carrying accumulating sediment down the road.

Culverts in high intensity burn areas are the most susceptible to fail. These culverts are susceptible to the greatest concentrations of debris flows and sedimentation. Culverts at risk that are also fish passage barriers are the highest concern because of the essential fish habitat.

## Future Trends

Forest and project level Roads Analysis will help the land manager to determine the current and future access needs for roads. This analysis will aid in a land management decision to maintain the road, close, or decommission it, and hydrologically stabilize it if treatment is needed. The management objective is to manage the forest transportation system to provide user safety with efficiency of operations in an environmentally responsible manner, and to continue road-related ecosystem restoration within the limits of current and likely funding levels. There are a number of opportunities to be proactive for this management objective.

Road management objectives establish the specific intended purpose of an individual road based on land management area direction and access management objectives. These objectives guide how a road is to be located, designed, constructed, operated, and maintained to meet the specific resource management objectives for the area accessed by the road. The objectives are also the basis for the road inventory, signing and mapping, and rules and regulations that apply to the use of the road.

Stabilized roads function in a more natural fashion with the environment regardless of whether the road is kept open, closed or decommissioned. Road stabilization is a system of treatments on a road designed to protect water resources and slope stability, including water quality, fisheries, and soil productivity. This will result in a road being able to better withstand storm and run-off events. This includes controlling drainage and sediment from road surfaces to minimize drainage impacts on other resources. This should make a road less dependent on many of the recurrent drainage maintenance activities.

An example of a road treatment would be to install long-term rolling dips into the road prism. These rolling dips are easily drivable, but also function to disburse water and reduce water diversion potential if an existing culvert plugs. Most dips need to have an aggregate base surface to prevent erosion and rutting, and control the sediment fines from washing. Other treatments include outsloping road sections to evenly disburse water; installing fill stabilization techniques such as rip rap or gabion walls; revegetation of cut and fill slopes; drivable fords; cross drainages; culvert end sections; upsizing culverts to meet a 100 year storm event; removing culverts and recontouring channels to their original contours; reducing fills over culverts; adding aggregate surfacing to a road; and adding drop inlets, to mention a few.

In the past it was perceived that only decommissioning or closing a road could help ecosystem restoration; however, with access needs we can actively promote stabilization of open Forest

Service roads as well. Each road is site specific as to what applications could be used. The road status will largely determine the type of treatments that will be used. After the stabilization process of an open road, the maintenance interval is reduced, and the road system functions in a more cost-effective manner. Decommissioning and stabilizing a road should have no more maintenance costs associated with it. Stabilizing and closing a road can be much like decommissioning it if the resource need is high. Currently, National Direction is to hydraulically stabilize all closed roads. Closing a road is usually more economical than decommissioning it, as culverts are not normally pulled out or channels recontoured. However, if the resource risk is very high a closed road may receive much of the same treatments as a decommissioned road by pulling culverts and recontouring stream channels. When a road is decommissioned it no longer exists on the system to be used in the future and is taken off the classified road inventory. Closing a road places it in a state of storage to use for future land management needs. A closed road remains on the system and is included in the inventory of system roads. The trend for the future is to continue to analyze and determine which roads to maintain, which roads to reduce the Maintenance Level on or which roads need the Maintenance Level increased, and which roads to close or decommission. The trend is to stabilize roads, as there are management opportunities and available funds to do so. Stabilization of a road may have the status as an open, closed, or decommissioned road. This proactive stance will support environmental restoration and economic sustainability.

## Management Opportunities

Because of the Biscuit fire and the potential risk for plugged culverts, road washouts, and road fill failures the following stabilization of roads at risk is recommended from the Biscuit Area Roads Analysis process. There are 10.8 miles of classified road located in the West Fork Illinois River Watershed that are located within the Biscuit fire boundary area.

**WEST FORK ILLINOIS RIVER Watershed**

***Roads to be Stabilized***

| HUC-5 | HUC-6 | Road No. | Length (Miles) |
|---|---|---|---|
| WEST FORK ILLINOIS RIVER | MIDDLE WEST FORK ILLINOIS RIVER | 4400445 | 2.73 |
| | MIDDLE WEST FORK ILLINOIS RIVER Total | | 2.73 |
| | ROUGH AND READY CREEK | 4400445 | 2.67 |
| | | 4400460 | 0.46 |
| | | 4400480 | 0.59 |
| | ROUGH AND READY CREEK Total | | 3.72 |
| WEST FORK ILLINOIS RIVER Stabilized Total Miles | | | 6.45 |

***There are no roads to be Closed or Decommissioned in the West Fork Illinois River Watershed.***

| | |
|---|---|
| Total miles of roads to have treatment in WF Illinois River Watershed | 6.45 |

## References:

Biscuit Fire Area Roads Analysis, April 2004, USDA Forest Service, Pacific Northwest Region, Rogue-Siskiyou National Forest, Ian Bayliss

## Changes in Current Conditions

Data gap. POC locations within the Biscuit fire perimeter are unknown. Until a new POC inventory is completed, all project sites will require an on site visit to determine presence or absence of POC and/or *Phytophthora lateralis* (PL), the pathogen that causes POC root disease.

## Future Trends

Data gap. An Inter-agency Supplemental Environmental Impact Statement (SEIS) for managing POC is being developed. The alternative selected in the Record of Decision for SEIS will determine future trends.

## Management Opportunities

### General

PL has been identified in the Woodcock Bog Area of Critical Environmental Concern (ACEC). When a management plan for the ACEC is developed, eradication treatments should be included.

Woodcock Bog had 18 POC tested for resistance to PL in 2001. Seven out of the 18 were found to be resistant and are now part of the resistance breeding program. This is one of the highest percentages of resistant trees per sample (39%) ever located. Additional samples should be taken in the bog and in other nearby ultramafic soils. POC from ultramafic soils are under represented in the resistance breeding program.

The Bureau of Land Management (Medford District) is evaluating section 9 in township 41 south, range 9 west as a potential Research Natural Area for the prevalence of rare plants, a number of *Darlingtonia* fens, and different plant associations including the Western White Pine-Tanoak/Huckleberry Oak/Common Beargrass association at low elevation (less than 2500 feet). This association has a POC component.

Complete the eradication/sanitation treatment along 4402 road between the BLM ownership (41-9-9) and O'Brien.

Sanitize any other roads in the watershed that remain open during the wet season and do not have PL.

Environmental analysis for any projects in areas with POC (includes access and egress routes) will include a PL control strategy.

Project design criteria for work in POC areas must include a determination of whether or not the area has root disease. Uninfested areas will be treated prior to infested areas. Most work should be limited to the dry season. Exceptions can be made for prescribed fire or in emergency situations which will have to be decided on a site specific basis. This does not mean that no precautions should be taken. Only that working in the wet season may be necessary to meet

prescribed fire or other management objectives. For wet season operations, unit scheduling (treat uninfested areas first, then infested areas), vehicle washing (before entering uninfested areas and before leaving infested areas), designation of access and egress routes or other measures should still implemented.

Add POC treatments to records for treated unit.

**Bough Collection**

Bough harvest should only be permitted when bough collection is accomplished via permit (negotiated contracts or by bid), requiring dry season operations (June through September), designation of access and egress routes, designation of parking areas, unit scheduling (collect all uninfested areas prior to infested areas), washing of boots and equipment, daily inspections, and easily identifiable areas where boughs are to be collected. No other special forest products permits will be issued where Port-Orford-cedar is present unless administration described above can be implemented.

**Engineering**

Washing areas should be at entry/exit points of the road system with Federal control. Washing areas should be situated so that runoff does not enter stream channels, ditchlines, or areas with POC. Washing areas should be mapped and recorded in a GIS layer so that they can be used in the future. Each road system that accesses areas with POC should have at least one washing area designated. Vehicle washing should take place as close as possible to infested sites. Ideally, vehicles should not travel for any substantial distance prior to being washed. Vehicles moving into uninfested areas may be washed miles away as long as they do not travel through infested areas to reach their destination. An evaluation to test the effectiveness of a vehicle washing treatment was conducted by the Southwest Oregon Forest Insect and Disease Service Center (SWOFIDSC) in June, 1999 (Goheen et al. 2000). Results indicated that there were large reductions in inoculum on the vehicles following washing.

Map water sources to show presence or absence of PL. Utilize uninfested water sources for planned activities such as road watering and other water distribution needs, or treat water with Clorox (Ultra, Institutional, as per label) to prevent the spread of PL.

As part of roads analysis, determine if areas with POC still require road access.

Road locations should be made, when possible, below POC areas or on opposite sides of ridges.

Where POC is concentrated within stream courses, road drainage should be designed to disperse water away from streams.

Locate and design waste areas so they do not spread PL spores. Use only approved waste areas if material must be transported.

Limit road construction and maintenance to the dry season (June through September). Minimize operations during periods of heavy rain regardless of time of season. However, this will not prevent the opening of plugged culverts or ditches or other maintenance when the need arises during periods of heavy rain.

Access to the project area should be along routes with least occurrence of infection sites.

**Eradication**

Use eradication and prescribed fire as management tools in areas with PL. Eradication is the killing of live POC in areas that have PL. Eradication distances will be a function of the crown radius of the infected tree. All healthy looking POC within three crown radii from the last infested tree will be killed. Removal of the tree is not required but may be necessary to allow for prescribed fire application. POC treatment areas should be treated as soon as possible after regenerating POC reach a height of 6 inches above ground level. This treatment should be incorporated into routine management such as roadside brushing, young stand management treatments, and pre-commercial thinning.

Eradication treatments may include the commercial harvest of POC products.

Eradication treatments can serve as a source for large wood used in aquatic habitat restoration. However it can also serve as a source for PL spores into the stream channel.

# Inventory

Map POC and PL locations in the watershed by plant association.

# Monitoring

Monitor for effectiveness of treatments. Monitoring can be at varying levels of intensity. Monitoring can include photo points of treated areas (pre and post treatment), formal plots (number of trees before and after sanitation or eradication treatments), or walk through inventory.

# Recreation

Route new trails (OHV, motorcycle, mountain bike, horse, and foot) away from areas with POC or PL. Established trails should be re-routed in the same manner where trails present risk to POC.

# Sanitation

Sanitation is the removal of live POC in areas without PL. Use sanitation to protect POC populations along roads that remain open during the wet season. Sanitation treatments may include the commercial harvest of POC products. Sanitation area width is recommended to be a minimum of 25 feet above the road or to the top of the cutbank. Below the road, recommended minimum width of 25 to 50 feet.

Sanitation treatments can serve as a source for large wood used in aquatic habitat restoration.

# Silviculture

Utilize resistant stock for reforestation. During calendar year 2002, 1.75 million resistant seed was produced and is available for reforestation in parts of the native range of POC; primarily

the northwest portion of the range. Additional resistant seed will become available in the future for other portions of the range.

Thinning treatments should break up POC continuity across thinning units. Spacing should be a minimum of four crown radii between leave POC.

Emphasize management of POC on sites where conditions make it likely that they will escape infection by PL, even if the pathogen has already been established nearby or may be introduced in the future. POC is favored above roads, uphill from creeks, on ridgetops, and on well-drained sites. Emphasis may include priority retention during thinning or other silvicultural treatments, and planting to increase the presence of POC in areas unfavorable to the pathogen.

## Ultramafic Soils

These soils are dry environments distinguished with a soil imbalance of the magnesium to calcium ratio. POC is among the few tree species that can grow in these soils and may provide a majority of or the only source of stream shading. Preventing the spread of PL into these areas should be a consideration in any project design.

### Wildfire Suppression

POC issues are secondary priority during wildfire suppression. While management objectives for POC are a concern, safety of firefighters and the public, as well as protection of property or protecting the fireline is always a higher priority. When practicable, management strategies to prevent spread of PL shall be incorporated into firefighting activities.

### References

Goheen, D.J.; Marshall, K.; Hansen, E.M.; and Betlejewski, F. 2000. Effectiveness of Vehicle Washing in Decreasing *Phytophthora lateralis* Inoculum: A Case Study. USDA-FS, SWOFIDSC-00-2 7p.