



## INTRODUCTION

The purpose of this project is to analyze Maintenance Level 3, 4, and 5 roadways within the Chequamegon-Nicolet National Forest (CNNF) and to provide scientific and quantitative information for the decision maker.

This appendix provides a summary of issue identification response comments for the Forest Level Roads Analysis Process for the CNNF in the Eagle River and Florence Ranger Districts. It also provides suggestions for opportunities to minimize impacts and improve the road system.

---

## FOREST ROAD 2150

### SUMMARY OF COMMENTS AND OPPORTUNITIES

One commenter indicated that maintenance concerns for Forest Road 2150 include: lack of closer gravel pit locations, lack of brushing, and snowmobile usage on the roadway that compacts the snow.

### COMMENTERS

Town of Florence

---

## FOREST ROAD 2151

### SUMMARY OF COMMENTS AND OPPORTUNITIES

One commenter indicated that maintenance concerns for Forest Road 2151 include: lack of closer gravel pit locations, lack of brushing, and snowmobile usage on the roadway that compacts the snow.

### COMMENTERS

Town of Florence

---

## FOREST ROAD 2154

### SUMMARY OF COMMENTS AND OPPORTUNITIES

One commenter indicated that maintenance concerns for Forest Road 2154 include: lack of closer gravel pit locations, lack of brushing, and snowmobile usage on the roadway that compacts the snow.

---



---

## COMMENTERS

Town of Florence

---

### FOREST ROAD 2174

#### SUMMARY OF COMMENTS AND OPPORTUNITIES

One commenter indicated that Forest Road 2174 would have increased traffic usage until 2007.

#### COMMENTERS

Bob Ellingson

---

### FOREST ROAD 2176

#### SUMMARY OF COMMENTS AND OPPORTUNITIES

One commenter indicated that Forest Road 2176 was a paved roadway that was later covered with gravel. The commenter suggested paving this roadway, because the dust that is produced from passing vehicles is bad.

#### COMMENTERS

Donald Schaeffer

---

### FOREST ROAD 2178

#### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters suggested that the stream crossing at Beaver Creek and Forest Road 2178 be repaired.

#### COMMENTERS

USDA Forest Service - CNNF

---

### FOREST ROAD 2182

#### SUMMARY OF COMMENTS AND OPPORTUNITIES

One commenter indicated that Forest Road 2182 was a paved roadway that was later covered with gravel. The commenter suggested paving this roadway, because the dust that is produced from passing vehicles is bad.

---



---

## COMMENTERS

Donald Schaeffer

---

### FOREST ROAD 2183

#### SUMMARY OF COMMENTS AND OPPORTUNITIES

One commenter indicated that Forest Road 2183 (Scott Lake Road) would have increased traffic usage until 2007.

Commenters also indicated that this roadway has wetland and maintenance problems and suggested relocating the roadway further north.

#### COMMENTERS

Bob Ellingson  
USDA Forest Service - CNNF

---

### FOREST ROAD 2192A

#### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters indicated that Forest Road 2192A has some steep slopes, which are causing erosion and sedimentation problems.

#### COMMENTERS

USDA Forest Service - CNNF

---

### FOREST ROAD 2205

#### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters suggested that Forest Road 2205 be paved.

#### COMMENTERS

USDA Forest Service - CNNF

---



## FOREST ROAD 2383

### SUMMARY OF COMMENTS AND OPPORTUNITIES

One commenter suggested that Forest Road 2383 be realigned in the SE ¼ of the NE ¼ of Section 30, T38N, R16E to allow access to Forest Road 2383G. The commenter indicated that a private landowner installed a gate that restricts public travel on Forest Road 2383G.

The Town has received a petition with approximately 500 signatures from local residents to realign Forest Road 2383.

### COMMENTERS

Dave Poquette

---

## FOREST ROAD 2404D

### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters suggested that there is an opportunity to relocate Forest Road 2404D out of the riparian zone and improve the stream crossings.

### COMMENTERS

USDA Forest Service - CNNF

---

## FOREST ROAD 2406

### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters suggested that there is an opportunity to improve access with Forest Road 2406 and Lilypad Lake and to decommission the end of the roadway at the lake carry-in location.

### COMMENTERS

USDA Forest Service - CNNF

---

## FOREST ROAD 2466

### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters suggested that there might be an opportunity to decommission a portion of Forest Road 2466 to reduce impacts to the riparian zone and stream crossings.

---



## COMMENTERS

USDA Forest Service - CNNF

---

### FOREST ROAD 2471

#### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters indicated that Forest Road 2471 has some steep slopes.

#### COMMENTERS

USDA Forest Service - CNNF

---

### FOREST ROAD 2471A

#### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters indicated that Forest Road 2471A has some steep slopes.

#### COMMENTERS

USDA Forest Service - CNNF

---

### FOREST ROAD 2472A

#### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters indicated that Forest Road 2472A has some steep slopes and suggested that there is an opportunity to decommission access from the east.

#### COMMENTERS

USDA Forest Service - CNNF

---

### FOREST ROAD 2568

#### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters indicated that Forest Road 2568 has some steep slopes and suggested a field inspection to identify potential erosion and maintenance problems. Commenters also suggested that there might be an opportunity to relocate the roadway to reduce impacts.

---



---

## COMMENTERS

USDA Forest Service - CNNF

---

### FOREST ROAD 3888

#### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters suggested that access for a portion Forest Road 3888 may be provided by Forest Road 2462. Therefore, an opportunity may exist to decommission a portion of Forest Road 3888 and remove the stream crossing.

As a note, this road is a Maintenance Level 2 roadway; therefore it is not shown on the Roads Analysis Matrix.

## COMMENTERS

USDA Forest Service - CNNF

---

### FOREST ROAD 604257

#### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters questioned if Forest Road 604257 was needed and suggested that if it is not needed, there may be an opportunity to decommission it.

## COMMENTERS

USDA Forest Service - CNNF