

-----Original Message-----

From: Linda & Denis [mailto:mzlinda@linctel.net]

Sent: Friday, September 30, 2011 10:07 AM

To: FS-comments-northern-helena

Subject: Mike horse dam clean up.

In the report I read,I noticed that the year of 2011 was called a abnormally wet year. Check the weather for years back, My wife and I have lived here for 30 years,believe me ,last year was the norm. The water gushing from the wellheads on section 35 and Mike Grimes property was A real wake up call. This water continues to the Blackfoot river.and beyond. Section 35 is unsatisfactory to use as a repository. Why can we not treat it in place with current technology ,using cement,and mixing it with the contaminants ,to make a rock that gets harder over the years,and then to control the possible leaching line the area with bentonite. Bear trap creek could be directed to a culvert or ditch around the affected area Our home lies directly across the road at the junction of .highway 200 and Meadow creek Thousands of loads of contaminants and return loads of cover soil will come by the house,dust flying and jake brakes screaming. Sounds like a funtime and place to be over the next few years.

Denis and Linda Bordeleau.

13708 Hwy 200 E

Lincoln Mt. 59639