



## INTRODUCTION

The purpose of this project is to analyze Maintenance Level 3, 4, and 5 roadways within the Chequamegon-Nicolet National Forest (CNNF) and to provide scientific and quantitative information for the decision maker.

This appendix provides a summary of issue identification response comments for the Forest Level Roads Analysis Process for the CNNF in the Great Divide Ranger District. It also includes suggestions for opportunities to minimize impacts and improve the road system.

---

## FOREST ROAD 150

### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters suggested that Forest Road 150 be relocated; however the opportunity to relocate this roadway may be limited due to private access.

### COMMENTERS

USDA Forest Service - CNNF

---

## FOREST ROAD 164

### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters suggested that the intersection of Forest Road 164 and Old Shady Road be relocated to avoid impacts.

### COMMENTERS

USDA Forest Service - CNNF

---

## FOREST ROAD 167

### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters suggested that the intersection at Forest Road 167 and Forest Road 327 be relocated.

### COMMENTERS

USDA Forest Service - CNNF

---



## FOREST ROAD 183

### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters suggested replacing the Brown Creek crossing along Forest Road 183.

### COMMENTERS

USDA Forest Service - CNNF

---

## FOREST ROAD 187

### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters indicated that portions of Forest Road 187 have steep slopes, which cause erosion and sedimentation. Commenters suggested realigning the “S” curve by Lake Three on Forest Road 187.

Commenters also indicated that the single lane bridge over Brunswailer River has limited visibility and stopping ability due to a hill. During the summer this roadway has an increased traffic load from tourists and it is a potential safety hazard.

### COMMENTERS

Town of Marengo  
USDA Forest Service - CNNF

---

## FOREST ROAD 195

### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters suggested replacing the East Twin Lake tributary crossing along Forest Road 195.

### COMMENTERS

USDA Forest Service - CNNF

---

## FOREST ROAD 198

### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters indicated that Forest Road 198 has some steep slopes, which are causing erosion and sedimentation problems. A portion of the roadway is located in a riparian zone. Commenters suggested that there is an opportunity to relocate a portion of the roadway to reduce impacts.

---



---

## COMMENTERS

USDA Forest Service - CNNF

---

### FOREST ROAD 202

#### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters indicated that Forest Road 202 has some steep slopes, which are causing drainage problems. A portion of the roadway has experienced flooding due to beaver damming.

#### COMMENTERS

USDA Forest Service - CNNF

---

### FOREST ROAD 212

#### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters suggested cutting the hill crest at the junction of USH 63 and Forest Road 212 for safety improvements. Commenters suggested adding gravel and blacktop to improve the roadway surface.

#### COMMENTERS

Town of Grandview, Howard Sibbald, Chairman  
USDA Forest Service - CNNF

---

### FOREST ROAD 213

#### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters indicated that the intersection of Forest Road 213 (Lake Owen Drive) and Forest Road 212 had degraded due to increased truck traffic.

#### COMMENTERS

Town of Drummond, Dale Siebert, Foreman

---



## FOREST ROAD 308

### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters indicated that Forest Road 308 has some steep slopes and suggested a field inspection to identify potential erosion and maintenance problems. Commenters also suggested that there might be an opportunity to relocate the roadway to reduce impacts.

### COMMENTERS

USDA Forest Service - CNNF

---

## FOREST ROAD 354

### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters suggested reconstructing Forest Road 354 to mitigate aquatic and water quality impacts.

### COMMENTERS

USDA Forest Service - CNNF

---

## FOREST ROAD 365

### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters indicated that Forest Road 365 parallels State Trunk Highway 63 and suggested there might be an opportunity to decommission all or a portion of Forest Road 365. Commenters also indicated that there is private ownership in the area, which may make it difficult to decommission.

### COMMENTERS

USDA Forest Service - CNNF

---

## FOREST ROAD 374

### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters indicated that the Town of Grandview would pave two miles of Forest Road 374 on the west and north side of Diamond Lake in 2003. The town requested minor maintenance work from the Forest Service to complete this project.

---



---

## COMMENTERS

Town of Grandview, Howard Sibbald, Chairman  
Town of Grandview, Mark Tody, Highway Department

---

### FOREST ROAD 378

#### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters indicated that Forest Road 378 has some major sedimentation problems. Some of the sedimentation problems were corrected in 2002; however problems still exist at Twenty Mile Creek. Commenters suggested that there might be an opportunity to relocate the roadway by Twenty Mile Creek to reduce impacts.

#### COMMENTERS

USDA Forest Service - CNNF

---

### FOREST ROAD 383

#### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters indicated that Forest Road 383 has some major sedimentation problems. Commenters suggested improving the stream crossings and relocating the roadway out of the riparian area to reduce impacts.

#### COMMENTERS

USDA Forest Service - CNNF

---

### FOREST ROAD 387

#### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters indicated that the culvert by Forest Road 387 and Hell Hole Creek has an ongoing problem with washouts.

#### COMMENTERS

Town of Marengo

---



---

## FOREST ROAD 390

### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters indicated that a portion Forest Road 390 has sediment problems. Commenters suggested reconstructing or relocating a portion of the roadway to reduce impacts. Commenters also suggested reconstructing the hills and curves on the roadway for safety improvements.

### COMMENTERS

USDA Forest Service - CNNF

---

## FOREST ROAD 604

### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters indicated that Forest Road 604 has annual flooding due to beaver damming. Commenters suggested that there might be an opportunity to relocate a portion of roadway to reduce impacts. However, private ownership may limit options for relocation.

### COMMENTERS

USDA Forest Service - CNNF

---

## FOREST ROAD 621

### SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters suggested that there is an opportunity to decommission Forest Road 621 if the local agencies approve.

### COMMENTERS

USDA Forest Service - CNNF

---

## STATE TRUNK HIGHWAY 77

### SUMMARY OF COMMENTS AND OPPORTUNITIES

One commenter indicated that State Trunk Highway 77 provides regional transportation needs to the area.

---

## **COMMENTERS**

Ashland County Highway Department, Emmer Shields Jr., Highway Commissioner

---

## **FOREST ROAD 849**

### **SUMMARY OF COMMENTS AND OPPORTUNITIES**

Commenters indicated that Forest Road 849 is steep and has erosion and maintenance problems.

## **COMMENTERS**

USDA Forest Service - CNNF