

TABLE 4. MIDDLE UPPER CITICO - SUMMARY OF RECOMMENDATIONS TO BE CONSIDERED (APRIL 2014)

ROAD #	ROAD NAME	APPROX. MILES IN WATERSHED	PRIVATE ACCESS	WILDFIRE SUPPRESSION USE	RECREATION/HERITAGE USE	WILDLIFE USE	VEGETATION MANAGEMENT	IMPACT TO STREAMS*	ENVIRONMENTAL RISK	RECOMMENDATIONS TO BE CONSIDERED
NATIONAL FOREST SYSTEM ROADS (NFSR)										
2604	GOLD CABIN BRANCH	2.82	no	yes	no	yes	yes	2		Manage as is. Linear wildlife opening and access to other openings, access to woodland units.
2659	DOUBLECAMP-JAKE BEST	13.56	no	yes	yes	yes	yes	4		Manage as is. Access to wildlife openings.
284	RAFTER	1.81	yes	yes	yes	yes	yes	1		Manage as is. Access to wildlife openings.
284F	OLD RAFTER	0.26	no	no	no	no	no	3		Decommission
284F	OLD RAFTER	0.27	no	yes	no	yes	yes	2		Manage as is. Access wildlife opening.
29	SOUTH FORK CITICO	0.07	no	no	yes	no	no	3		Manage as is.
29	SOUTH FORK CITICO	0.05	no	no	yes	no	no	3		Manage as is.
336	DOUBLECAMP REC.AREA	0.08	no	no	yes	no	no	3		Manage as is.
345	INDIAN BOUNDARY	2.45	no	yes	yes	no	yes	2		Manage as is.
345-1	INDIAN BDY. LOOP ENT.	0.18	no	no	yes	no	no	2		Manage as is.
345A	INDIAN BOUNDARY LOOP A	0.33	no	no	yes	no	no	2		Manage as is.
345B	INDIAN BOUNDARY LOOP B	0.31	no	no	yes	no	no	2		Manage as is.
345C	INDIAN BOUNDARY LOOP C	0.41	no	no	yes	no	no	2		Manage as is.
345C-1	INDIAN BNDY LOOP C CROSSOVER	0.08	no	no	yes	no	no	2		Manage as is.
345D	INDIAN BOUNDARY BOAT RAMP	0.18	no	no	yes	no	no	2		Manage as is.
345D-1	INDIAN BOUND NEW DUMP STATION	0.11	no	no	yes	no	no	2		Manage as is.
345E	INDIAN BDY DAY USE NORTH	0.18	no	no	yes	no	no	2		Manage as is.
345F	INDIAN BOUNDARY OVERFLOW	0.27	no	no	yes	no	no	2		Manage as is.
345G	INDIAN BDY DAY USE SOUTH	0.46	no	no	yes	yes	no	2		Manage as is. Access wildlife opening.
345G-1	INDIAN BDY. TRAILER DUMP	0.07	no	no	yes	no	no	2		Manage as is.
345H	INDIAN BDRY SERVICE RD.	0.13	no	no	yes	yes	no	2		Manage as is. Access wildlife opening.
345H1	FT. LOUDON ELEC. @ INDIAN BDY	0.14	no	no	no	yes	no	2		Manage as is. Access wildlife opening.
345J	INDIAN BDY. ADM. RD.	0.10	no	no	no	no	no	2		Manage as is.
35	CITICO CREEK SOUTH	1.32	yes	yes	no	yes	yes	1		Access wildlife opening. See Middle Tellico Assessment.
35-1	CITICO CREEK NORTH	9.30	no	yes	yes	yes	yes	4		Manage as is. thru road; access to wildlife areas.
35A	JAKE BEST CAMPGROUND	0.10	no	no	yes	no	no	2		Manage as is.
35B	CITICO SLIDE	0.09	no	no	no	no	no	1		Decommission.
35C	OLD CITICO	0.36	no	yes	yes	yes	no	2		Access wildlife opening; Decommission
35D	CRANE ISLAND DISPERSED CAMPING	0.05	no	no	yes	no	no	3		Manage as is.
36	TAVERN BRANCH SOUTH	1.40	no	yes	no	yes	yes	1		Manage as is. Access wildlife opening; See TAP report for Ballplay Cr. watershed for management of section outside of Middle Upper Citico Cr. watershed
36-1	TAVERN BRANCH NORTH	3.36	no	yes	no	yes	yes	3		Decommission approx. 3.02 mi from #35-1 to top of ridge
402301	COWCAMP	2.00	no	yes	no	no	yes	2		Manage as is.
402302	COWCAMP SPUR	0.57	no	yes	no	no	yes	2		Manage as is.
402303	GLADYS BRANCH	0.50	no	yes	no	no	no	1		Decommission

TABLE 4. MIDDLE UPPER CITICO - SUMMARY OF RECOMMENDATIONS TO BE CONSIDERED (APRIL 2014)

ROAD #	ROAD NAME	APPROX. MILES IN WATERSHED	PRIVATE ACCESS	WILDFIRE SUPPRESSION USE	RECREATION/HERITAGE USE	WILDLIFE USE	VEGETATION MANAGEMENT	IMPACT TO STREAMS*	ENVIRONMENTAL RISK	RECOMMENDATIONS TO BE CONSIDERED
NATIONAL FOREST SYSTEM ROADS (NFSR)										
40251	MILLER RIDGE SPUR	1.22	no	yes	yes	yes	yes	1		Decommission approx. 0.88 mi. from #36-1 to #36
40252	BURNT STATION	0.56	no	yes	no	yes	yes	1		Decommission approx. 0.4 mi. from intersection w/ #36 to end of road
403101	FOOTES CREEK	0.93	no	yes	no	yes	yes	1		Manage as is. Linear wildlife opening, access to woodland unit.
40321	EAST MILLER RIDGE	0.99	no	yes	yes	yes	yes	1		Manage as is. Linear wildlife opening.
40401	DEBETY GAP	0.62	no	yes	no	yes	no	1		Linear wildlife opening. Decommission & manage as LWO.
40402	BORROW PIT	0.18	no	no	no	no	no	1		Decommissioned.
40403	BSA CAMPGROUND	0.10	yes	yes	yes	yes	yes	1		Manage as is. Accesses Boy Scout camping area
404201	FLATS CREEK	1.04	no	yes	no	yes	yes	1		Manage as is. Linear wildlife opening.
40480	OLD WARDEN STATION	0.15	no	no	no	no	no	1		ALREADY DECOMMISSIONED
440601	BLUE MOUNTAIN	0.31								Access to woodlands. Refer to adjacent watersheds.
440903	LULA GAP	0.21								Refer to adjacent watersheds.
5003	BARKCAMP	0.71	no	yes	yes	no	yes	2		Manage as is. Seasonal opening for hunting.
5003	BARKCAMP	2.80	no	yes	yes	no	yes	2		Manage as is. Seasonal opening for hunting.
5022	BIVENS BRANCH	2.09	no	yes	yes	no	yes	3		Manage as is. Seasonal opening for hunting.
5022A	BIVENS BR.SPUR A	0.25	no	yes	no	yes	yes	1		Manage as is.
59A	DOUBLECAMP SPUR	0.11	no	no	no	yes	yes	1		Manage as is. Access wildlife opening.
59B	COLD SPRINGS SPUR	0.12	yes	no	no	no	no	1		Manage as is.

UNAUTHORIZED ROADS

*1=LOW, 2=MEDIUM, 3=HIGH, 4=VERY HIGH, 5=SEVERE

TABLE 4. MIDDLE UPPER CITICO - SUMMARY OF RECOMMENDATIONS TO BE CONSIDERED (APRIL 2014)

ROAD #	ROAD NAME	APPROX. MILES IN WATERSHED	PRIVATE ACCESS	WILDFIRE SUPPRESSION USE	RECREATION/ HERITAGE USE	WILDLIFE USE	VEGETATION MANAGEMENT	IMPACT TO STREAMS*	ENVIRONMENTAL RISK	RECOMMENDATIONS TO BE CONSIDERED
NATIONAL FOREST SYSTEM ROADS (NFSR)										

Miles of system routes to be considered for decommissioning:	
Roads:	6.13
Trails:	0.00
Total:	6.13

Miles of unauthorized routes to be decommissioned:	
	0.00

Total miles of all routes to be decommissioned:	
	6.13

Miles of unauthorized routes to consider adding to system:	
Roads:	0.00
Trails:	0.00
Total:	0.00

Net change to transportation system mileage:	
Roads:	-6.13
Trails:	0.00
Total:	-6.13