

Transition EIS: Preliminary Alternative 2
Area 18b - Well and Road Mitigations

Well No.	Area No.	Well Concerns	Mitigation
M185-2301	18b	Seeps	No surface occupancy
M185-2301	18b	Fell within 50' of an intermittent stream	
	18b	Fell within slopes of greater than 40% (steep slopes)	
M185-2304	18b	Wet area	Moved well 50' south
M193-2308	18b	Stream and seep	Moved well 50'
M193-2308	18b	Fell within 50' of intermittent streams (25% Slope)	Moved well north

Road No.	Area No.	Road Concerns	Mitigation
TE102067	18b	Fell within 100' of a seep	Crossing; Apply best management practices
TE102067	18b	Fell within 50' of an intermittent stream	Crossing; Apply best management practices