

**Table 3.1  
Summary of ARARs (continued)**

<b>Action Specific ARARs</b>		
<b>Media</b>	<b>Citation</b>	<b>Description</b>
<b>Hazardous Substances</b>	National Oil and Hazardous Substances Pollution Contingency Plan (NCP) Title 40 CFR Chapter I, Part 300	The NCP provides guidelines and procedures for federal response to releases and threatened releases of hazardous substances, pollutants, or contaminants.
	Comprehensive Environmental Response Conservation and Liability Act (CERCLA) 42 U.S.C. 9601, et seq.	Establishes broad federal authority to respond to releases or threatened releases of hazardous substances that may endanger public health or the environment.
<b>Hazardous Waste</b>	Resource Conservation and Recovery Act (RCRA) 42 USC Sections 6901-6987; 40 CFR Part 265	Regulations for the generation, transportation, storage and disposal of hazardous waste. Specific closure, performance and design requirements for hazardous waste landfills and impoundments. Mine wastes are exempt from regulation under RCRA
<b>Worker Protection</b>	Occupational Safety and Health Act (OSHA)	Regulates worker health and safety. Potentially applicable removal action construction activities.
<b>To Be Considered</b>		
<b>Archaeology and Historic Preservation</b>	Secretary of the Interior's Standards and Guidelines (AHP). 48 FR 44716-44740	Sets acceptable multimedia criteria for common chemicals of concern (heavy metals) as they relate to recreational use and wildlife habitat on BLM lands.
<b>Human and Ecological Risk Assessment</b>	Risk Management Criteria for Metals at BLM Mining Sites, BLM Technical Note 390 revised, 1996.	Sets acceptable multimedia criteria for common chemicals of concern (heavy metals) as they relate to recreational use and wildlife habitat on BLM lands.
	Risk Assessment Guidance for Superfund: Volume 1 – Human Health Evaluation Manual	Provides guidance for procedures to establish quantitative risks from exposure to various chemicals that enter the environment.
<b>Radiation</b>	EPA Superfund Preliminary Remediation Goals for Radionuclides	Tabulated risk-based cleanup goals for soil and tap water ingestion that, if exceeded, may warrant further action.
	Soil Screening Guidance for Radionuclides: User's Guide: EPA/540-R-00-007, October 2000	Provides guidelines to calculate risk-based, site-specific, soil screening levels for radionuclides in soil.
	EPA Directive 9200.4-35P Remediation Goals for Radioactively Contaminated CERCLA Sites Using the Benchmark Dose Cleanup Criteria in 10 CFR Part 40 Appendix A, I, Criterion 6(6), April 2000.	Establishes the relationship between the soil standards set under 40 CFR 192 and the radium benchmark approach under 10 CFR 40 Appendix A, I, Criterion 6(6)

\* 40 CFR Part 261.4 (b) (7) specifically excludes from the definition of hazardous waste any "solid waste from the extraction, beneficiation, and processing of ores and minerals (including coal, phosphate rock, and overburden from the mining of uranium ore).