

## 2020 ECRD – Gay Spring Aquatic Restoration/Aspen Hollow Lands SUP Review (03/24/2020)

Gay Spring Restoration - T. 19 S., R. 28 E., Sec. 8

- No Lands SUPs identified within project area.
- No ditches identified within project area.
- No boundary nor private access issues identified.



No OWRD PODs/water rights found per <https://apps.wrd.state.or.us/apps/gis/wr/Default.aspx>.

