

CAMPGROUND/TRAILHEAD INSPECTION FORM

CAMPGROUND: Campo Alto

DATE: 6/8/15 L.Brannan-FS, B.Smith & D.Martin Vols.

SITE #: 1 Or Location Description: adjacent to dirt road to communication site



Table Info:

Type: Heavy Wood Light Wood/Pipe Concrete/Wood Concrete Well Casing/Wood Metal

Condition: Good Fair Needs Paint Needs Repair and Paint Replace Removed

Stove Type: Metal Ring 18" ADA

Condition: Excellent Good Needs Repair/Maintenance Replace Removed

Remarks (i.e. Repairs needed, etc): new fire ring

SITE #: 2 Or Location Description:



Table Info:

Type: Heavy Wood Light Wood/Pipe Concrete/Wood Concrete Well Casing/Wood Metal

Condition: Good Fair Needs Paint Needs Repair and Paint Replace Removed

Stove Type: Metal Ring 18" ADA

Condition: Excellent Good Needs Repair/Maintenance Replace Removed

Remarks (i.e. Repairs needed, etc): new fire ring

SITE #: 3 Or Location Description: further south beyond site #2



Table Info:

Type: Heavy Wood Light Wood/Pipe Concrete/Wood Concrete Well Casing/Wood Metal

Condition: Good Fair Needs Paint Needs Repair and Paint Replace Removed

Stove Type: Metal Ring 18" ADA

Condition: Excellent Good Needs Repair/Maintenance Replace Removed

Remarks (i.e. Repairs needed, etc): new fire ring

SITE #: 4 Or Location Description: at entrance road junction with campground spur road



Table Info:

Type: Heavy Wood Light Wood/Pipe Concrete/Wood Concrete Well Casing/Wood Metal

Condition: Good Fair Needs Paint Needs Repair and Paint Replace Removed

Stove Type: Metal Ring <18"

Condition: Excellent Good Needs Repair/Maintenance Replace Removed

Remarks (i.e. Repairs needed, etc): table needs plank; remove rock around fire ring

SITE #: 5 Or Location Description: northwest of entrance road and campground spur road

No Photo

Table Info:

Type: Heavy Wood Light Wood Concrete/Wood Concrete Well Casing/Wood Metal

Condition: Good Fair Needs Paint Needs Repair and Paint Replace Removed

Stove Type: None

Condition: Excellent Good Needs Repair/Maintenance Replace Removed

Remarks (i.e. Repairs needed, etc): existing campsite marker but no table or fire ring: install new table and ADA fire ring

SITE #: 6 Or Location Description:



Table Info:

Type: Heavy Wood Light Wood/Pipe Concrete/Wood Concrete Well Casing/Wood Metal

Condition: Good Fair Needs Paint Needs Repair and Paint Replace Removed

Stove Type: Metal Ring 18" ADA

Condition: Excellent Good Needs Repair/Maintenance Replace Removed

Remarks (i.e. Repairs needed, etc):

SITE #: 7 Or Location Description: across campground spur road from site #8



Table Info:

Type: Heavy Wood Light Wood Concrete/Wood Concrete Well Casing/Wood Metal

Condition: Good Fair Needs Paint Needs Repair and Paint Replace Removed

Stove Type: Metal Ring 7" Non-ADA

Condition: Excellent Good Fair Needs Repair/Maintenance Replace Removed

Remarks (i.e. Repairs needed, etc): add carsonite campsite marker; no table; install new table; remove rocks around fire ring

SITE #: 8 Or Location Description:



Table Info:

Type: Heavy Wood Light Wood Concrete/Wood Concrete Well Casing/Wood Metal

Condition: Good Fair Needs Paint Needs Repair and Paint Replace Removed

Stove Type: Metal Ring 7" Non-ADA

Condition: Excellent Good Fair Needs Repair/Maintenance Replace Removed

Remarks (i.e. Repairs needed, etc): no table; install new table & remove rocks around fire ring

SITE #: 9 Or Location Description:



Table Info:

Type: Heavy Wood Light Wood Concrete/Wood Concrete Well Casing/Wood Metal

Condition: Good Fair Needs Paint Needs Repair and Paint Replace Removed

Stove Type: Metal Ring 7" Non-ADA

Condition: Excellent Good Fair Needs Repair/Maintenance Replace Removed

Remarks (i.e. Repairs needed, etc): no table; install new table & remove rocks around fire ring

SITE #: 10 Or Location Description:



Table Info:

Type: Heavy Wood Light Wood Concrete/Wood Concrete Well Casing/Wood Metal

Condition: Good Fair Needs Paint Needs Repair and Paint Replace Removed

Stove Type: Metal Ring 7" Non-ADA

Condition: Excellent Good Fair Needs Repair/Maintenance Replace Removed

Remarks (i.e. Repairs needed, etc): replace one bench seat

SITE #: 11 Or Location Description:



Table Info:

Type: Heavy Wood Light Wood Concrete/Wood Concrete Well Casing/Wood Metal

Condition: Good Fair Needs Paint Needs Repair and Paint Replace Removed

Stove Type: Metal Ring 7" Non-ADA

Condition: Excellent Good Fair Needs Repair/Maintenance Replace Removed

Remarks (i.e. Repairs needed, etc): no table; install new table; new number decals on carsonite campsite marker

SITE #: 12 Or Location Description:



Table Info:

Type: Heavy Wood Light Wood/Pipe Concrete/Wood Concrete Well Casing/Wood Metal

Condition: Good Fair Needs Paint Needs Repair and Paint Replace Removed

Stove Type: Concrete/Klamath

Condition: Excellent Good Needs Repair/Maintenance Replace Removed

Remarks (i.e. Repairs needed, etc): table silted in/buried to bench level; install new table and ADA fire ring; remove Klamath & rock fire ring

SITE #: 13 Or Location Description:



Table Info:

Type: Heavy Wood Light Wood/Pipe Concrete/Wood Concrete Well Casing/Wood Metal

Condition: Good Fair Needs Paint Needs Repair and Paint Replace Removed

Stove Type: Concrete/Klamath

Condition: Excellent Good Needs Repair/Maintenance Replace Removed

Remarks (i.e. Repairs needed, etc): remove Klamath & replace w/ ADA fire ring; no site number-add carsonite campsite sign

SITE #: 14 Or Location Description:



Table Info:

Type: Heavy Wood Light Wood/Pipe Concrete/Wood Concrete Well Casing/Wood Metal

Condition: Good Fair Needs Paint Needs Repair and Paint Replace Removed

Stove Type: Concrete/Klamath

Condition: Excellent Good Needs Repair/Maintenance Replace Removed

Remarks (i.e. Repairs needed, etc): no site number; table silted in on one side-too high on other; install new table, ADA fire ring and carsonite site marker

SITE #: 15 Or Location Description: site to left beyond site #16 & beyond grove of trees with site marker



Table Info:

Type: Heavy Wood Light Wood Concrete/Wood Concrete Well Casing/Wood Metal

Condition: Good Fair Needs Paint Needs Repair and Paint Replace Removed

Stove Type: Metal Ring 7" Non-ADA

Condition: Excellent Good Fair Needs Repair/Maintenance Replace Removed

Remarks (i.e. Repairs needed, etc): no table; add table

SITE #: 16 Or Location Description:



Table Info:

Type: Heavy Wood Light Wood/Pipe Concrete/Wood Concrete Well Casing/Wood Metal

Condition: Good Fair Needs Paint Needs Repair and Paint Replace Removed

Stove Type: Concrete/Klamath

Condition: Excellent Good Needs Repair/Maintenance Replace Removed

Remarks (i.e. Repairs needed, etc): replace Klamath stove with ADA fire ring

SITE #: 17 Or Location Description: by rock outcrop



Table Info:

Type: Heavy Wood Light Wood/Pipe Concrete/Wood Concrete Well Casing/Wood Metal

Condition: Good Fair Needs Paint Needs Repair and Paint Replace Removed

Stove Type: Metal Ring 18" ADA

Condition: Excellent Good Needs Repair/Maintenance Replace Removed

Remarks (i.e. Repairs needed, etc): no campsite marker; install carsonite campsite marker

SITE #: Group Camp #1 (formerly campsite #18) Or Location Description: farthest northwest end of spur road



Table Info:

Type: Heavy Wood Light Wood/Pipe Concrete/Wood Concrete Well Casing/Wood Metal

Condition: Good Fair Needs Paint Needs Repair and Paint Replace Removed

Stove Type: Concrete/Klamath

Condition: Excellent Good Needs Repair/Maintenance Replace Removed

Remarks (i.e. Repairs needed, etc): six (6) extra long group tables in good condition; Klamath stove, rock foundation fire pit with hand-crank, adjustable height, metal bbq grill and adjoining open fire platform

SITE #: Group Camp #2 (formerly campsite #19) Or Location Description: farthest southwest end of spur road



Table Info:

Type: Heavy Wood Light Wood/Pipe Concrete/Wood Concrete Well Casing/Wood Metal

Condition: Good Fair Needs Paint Needs Repair and Paint Replace Removed

Stove Type: Concrete/Klamath

Condition: Excellent Good Fair Needs Repair/Maintenance Replace Removed

Remarks (i.e. Repairs needed, etc): one (1) extra long group table missing bench seat on one side; reinstall pipe supports and bench seat; Klamath stove and adjoining rock foundation open fire platform: rock and walls are cracked crumbling; replace w/ new ADA fire ring

Miscellaneous: Deep pit BBQ

Location: in-between Group Camps #1 & #2



Description: below-ground concrete bbq pit with iron doors

Dimensions: ?????

Remarks: portions of above-ground concrete crumbling; FS Yale lock