

CAMPGROUND/TRAILHEAD RESTROOM INSPECTION FORM

CAMPGROUND/TRAILHEAD: Campo Alto

DATE: 6/8/15 L.Brannan-FS, B.Smith & D.Martin Vols.

RESTROOM #: 5794.WC2 Or Location Description: At entrance road; adjacent to Campsite #4



Exterior Info:

Type of Restroom: Wooden **Dimensions:** ????

- Walls: Good Condition Needs Painting Needs Repair and Paint Replace Restroom
Roof/Shingles: Good Condition Light Maintenance Heavy Maintenance Replace roof/shingles
Privacy Panels: Good Condition Needs Painting Needs Repair and Paint Replace

Remarks (i.e. Repairs needed, etc): one privacy panel gone and one loose

Interior Info:

Number of Vaults: 2

- Riser/Seat: Excellent Good Condition Light Maintenance Replace Riser and/or Seat
Walls: Good Condition Needs Painting Needs Repair and Paint Replace Restroom
Windows/Vents: Good Condition Needs Screen/Windows Needs Privacy Slats Installed

Remarks (i.e. Repairs needed, etc): womens: 4 risers; mens: 2 risers and 1 urinal

RESTROOM #: 5794.WC3 **Or Location Description:** near group camps



Exterior Info:

Type of Restroom: Wooden **Dimensions:** ????

- Walls: Good Condition Needs Painting Needs Repair and Paint Replace Restroom
- Roof/Shingles: Good Condition Light Maintenance Heavy Maintenance Replace roof/shingles
- Privacy Panels: Good Condition Needs Painting Needs Repair and Paint Replace

Remarks (i.e. Repairs needed, etc): privacy panels need boards; foundation being undermined by ground squirrels on all sides

Interior Info:

Number of Vaults: 2

- Riser/Seat: Excellent Good Condition Light Maintenance Replace Riser and/or Seat
- Walls: Good Condition Needs Painting Needs Repair and Paint Replace Restroom
- Windows/Vents: Good Condition Needs Screen/Windows Needs Privacy Slats Installed

Remarks (i.e. Repairs needed, etc): womens: 4 risers; mens: 2 risers and 1 urinal