



Source: Triad/Holmes Associates, 2019.
 Notes:
 1. Trees only surveyed in vicinity of cabins.
 2. Waste pile locations and dimensions are approximate, based on field sketches and site topography.

Figure 11. Extent of Metals-Impacted Soil in Cabins Area
 Supplemental Characterization Report for the Cabins Area at Mammoth Mill
 Inyo National Forest, Mono County, California

2019-10-14 W:\2017\20171015_USFS_Mammoth_Mill\Projects\002_Sampling_Results\11_Extent_Metals_Impact.mxd ERRG-Albuquerque simon.cardinale