TABLE OF CONTENTS

Chapter/Section		Page
1	**Introduction**	1-1
1.1	Project Goals and Objectives	1-2
2	**Geologic and Hydrologic Setting and Geomorphic Processes**	2-1
2.1	Introduction	2-1
2.2	Reconnaissance Survey Assessments	2-1
2.3	Hydrologic Setting	2-9
2.4	Geomorphic Assessment	2-14
2.5	Dominant Discharge	2-19
2.6	Aerial Assessment	2-21
2.7	References	2-27
3	**Biological Setting and Processes**	3-1
3.1	Introduction	3-1
3.2	Methods	3-1
3.3	Plant Communities	3-2
3.4	Aquatic Ecosystems	3-35
3.5	Terrestrial Wildlife	3-52
3.6	References	3-53
4	**Impact of Roads, Parking Lots, Livestock Grazing, and Human Infrastructure on Wetland Function and Processes**	4-1
4.1	Introduction	4-1
4.2	Aerial Photo Time Series Analysis	4-1
4.3	Effects of Infrastructure Development	4-9
4.4	Grazing History and Effects	4-17
4.5	References	4-24
5	**Fire History and Management**	5-1
5.1	Human Influences on Fire Processes	5-1
5.2	Fire Regimes and Ecological Consequences	5-4
5.3	Role of Fire for Habitat Enhancement	5-8
5.4	References	5-11
6	**Role of the Washoe Tribe in the Watershed**	6-1
6.1	Historical Background	6-1
6.2	Traditional Land Use	6-5
6.3	Present Day Land Use	6-8

TABLE OF CONTENTS (CONTINUED)

Chapter/Section **Page**

6.4 Watershed Policy and Legislation: Forest Service – Washoe Tribe Relations 6-8
6.5 Washoe Tribe Watershed Management Goals.....6-9
6.6 References 6-11

7 Geomorphic, Hydraulic, and Biotic Basis of Engineering Design 7-1
7.1 Natural Processes and Process Alterations 7-1
7.2 Restoration Opportunities Matrix and Map 7-9
7.3 Parking Lot and Access Road Study.....7-9
7.4 Trails and Public Access Options Study 7-19
7.5 Swale Restoration Study 7-19
7.6 Sewer Line Study and Bathroom Options 7-21
7.7 Management Issues.....7-23
7.8 References 7-28

8 Conceptual Restoration Plans 8-1
8.1 Scenario 1 8-1
8.2 Scenario 2 8-4
8.3 Scenario 3 8-5
8.4 Scenario 4 8-7

Tables **Page**

2.3-1 Flood frequency estimates for Taylor and Tallac Creeks 2-11
2.3-2 Lake Tahoe Elevation Summary Data.....2-12

3.3-1 Estimated Acreages of Plant Communities and Vegetated Aquatic Ecosystems in the Focal Study Area 3-3
3.4-1 Fish Species in the Tahoe Basin 3-36
3.4-2 Summary of 2004 Fish Sampling in Taylor and Tallac Creeks.....3-40
3.4-3 Biological Metric Used in Bioassessment Procedures.....3-51

4.3-1 Runoff Statistics from Existing Parking Lots and Access Roads.....4-14
4.3-2 Average Annual Pollutant Loads from Existing Parking Lots and Access Roads 4-14

7.2-1 Restoration Opportunities Matrix 7-11
7.3-1 Parking Lot Alternative Study 7-18
7.3-2 Average Annual Load from Runoff.....7-18
7.4-1 Trails and Public Access Options.....7-20
7.5-1 Theoretical Wetland Area: Pre- and Post-Surface Modification 7-21

TABLE OF CONTENTS (CONTINUED)

Exhibits **Page**

1-1 Taylor Creek and Tallac Creek Watersheds 1-5
1-2 Reconnaissance Area 1-7
1-3 Focal Study Area 1-9

2.2-1 Generalized Assessment of Channel Conditions 2-29
2.2-2 Location of Pictures in Appendices A and B 2-30
2.3-1 Location Map and Drainage Basins 2-31
2.3-2 Annual Precipitation Correlation 2-32
2.3-3 Time Series of Annual Precipitation 2-33
2.3-4 Taylor Creek Daily Discharge (1968–1992) 2-34
2.3-5 Regulated Flood Frequency for Taylor Creek 2-35
2.3-6 Flood Frequency for Taylor and Tallac Creeks 2-36
2.3-7 Historic Lake Tahoe Water Levels (1885–1923) 2-37
2.3-8 Lake Tahoe End of Month Water Levels (1900–1950) 2-38
2.3-9 Lake Tahoe End of Month Water Levels (1950–2003) 2-39
2.3-10 Water Surface Elevation ±0.5 ft Occurring most Frequently: Full Record 2-40
2.3-11 Annual Lake Tahoe Minimum, Maximum, and Mean Water Surface 2-41
2.3-12 Percentage Exceedance Plot of Lake Tahoe Elevation Data 2-42
2.3-13 Water Surface Elevation ±0.5 ft Frequency of Occurrence Since 1944 2-43
2.3-14 Piezometer Locations within Project Area 2-44
2.3-15 Year 2003 Groundwater Profiles 2-45
2.4-1 Geologic Setting 2-46
2.4-2 Geology of Project Site 2-47
2.4-3 Longitudinal Profile of Creeks 2-48
2.4-4 Geomorphic Evolution 2-49
2.4-4 Geomorphic Evolution 2-50
2.4-4 Geomorphic Evolution 2-51
2.4-4 Geomorphic Evolution 2-52
2.4-4 Geomorphic Evolution 2-53
2.4-5 Headcut on Taylor Creek near Lake Tahoe 2-54
2.4-6 Channel Incision and Bank Erosion on Tallac Creek 2-55
2.4-7 Sediment Deposition in Tallac Creek at Spring Creek Road 2-56
2.4-8 Temporal Evolution of Tallac and Taylor Creek Wetlands 2-57
2.5-1 Taylor Creek Survey Location 2-58
2.5-2 Taylor Creek Cross Section for Dominant Discharge 2-59
2.5-3 Estimated Dominant Discharge for Taylor Creek at SR 89 Bridge 2-60
2.5-4 Tallac Creek Survey Location 2-61
2.5-5 Tallac Creek Cross Section for Dominant Discharge 2-62
2.5-6 Estimated Dominant Discharge for Tallac Creek at Lake Tahoe 2-63

TABLE OF CONTENTS (CONTINUED)

Exhibits **Page**

2.6-1 Mouth Dynamics: Taylor Creek 2-65
2.6-2 Mouth Dynamics: Tallac Creek 2-67
2.6-3 Channel Alignment: Taylor Creek 2-69
2.6-4 Taylor Creek Overbank Flows....2-71
2.6-5 Channel Alignment: Tallac Creek 2-73
2.6-6 1940 Ortho with Theoretical Inundation Overlay 2-75
2.6-7 1952 Ortho with Theoretical Inundation Overlay 2-77
2.6-8 1967 Ortho with Theoretical Inundation Overlay 2-79
2.6-9 1976 Ortho with Theoretical Inundation Overlay 2-81
2.6-10 1983 Ortho with Theoretical Inundation Overlay 2-83
2.6-11 1995 Ortho with Theoretical Inundation Overlay 2-85
2.6-12 1997 Ortho with Theoretical Inundation Overlay 2-87
2.6-13 2000 Ortho with Theoretical Inundation Overlay 2-89
2.6-14 2003 Ortho with Theoretical Inundation Overlay 2-91

3.3-1 Plant Communities and Aquatic Ecosystems....3-61
3.3-2 Plant Communities and Aquatic Ecosystems with Lagoon from 2000 3-63
3.3-3 Elevation Surface Model for Taylor and Tallac Marsh....3-65
3.3-4 Plant Distribution along an Environmental Gradient 3-66
3.3-5 Soils....3-67
3.3-6 Lodgepole Pine and Aspen Regeneration....3-69
3.3-7 Microstructure in a Montane Meadow....3-70
3.3-8 Lagoon on Taylor and Tallac Creek 3-71
3.3-9 Succession of Lagoon to Meadow....3-72
3.4-1 Fish Sampling Locations....3-73

4.2-1 7-13-40....4-27
4.2-2 8-14-52....4-29
4.2-3 1967 (5-2-67 and undated) 4-31
4.2-4 8-24-76....4-33
4.2-5 9-10-83....4-35
4.2-6 8-19-95....4-37
4.2-7 8-14-97....4-39
4.2-8 7-12-00....4-41
4.2-9 10-9-03....4-43
4.2-10 Infrastructure 7-13-40 4-45
4.2-11 Infrastructure 1967....4-47
4.2-12 Infrastructure 8-24-76 4-49
4.2-13 Infrastructure 9-10-83 4-51

TABLE OF CONTENTS (CONTINUED)

Exhibits **Page**

4.2-14 Infrastructure, Disturbance, and Fire 8-19-95 4-53
4.2-15 Infrastructure, Disturbance, and Fire 10/9/03 4-55
4.2-16 Jeffrey Pine and Lodgepole Pine 4-57
4.2-17 Aspen and Beaver 4-59
4.2-18 Wetland System 4-61
4.3-1 Infrastructure 4-63
4.3-2 Tree and Shrub Encroachment of Wet Swale 4-65
4.3-3 Theoretical Inundation at Legal Maximum Level 4-66
4.3-4 Existing Parking Lots and Roads on 1940 Orthophoto 4-67
4.3-5 Existing Parking Lots and Roads on 2003 Orthophoto 4-68
4.3-6 Piezometer Locations 4-69
4.3-7 Piezometer Observations in Relation to Lake Level 4-70
4.3-8 Piezometer Locations 4-71
4.4-1 Baldwin Grazing Allotment 4-73
4.4-2 Differences in Vegetation between Grazed and Ungrazed Meadow 4-75
4.4-3 Grazing Impacts in Drier Meadow 4-76
4.4-4 Volunteer Trail Development 4-77
4.4-5 Streambank Trampling and Soil Disturbance 4-78

5-1 Fire History 5-13

7.2-1 Restoration Opportunities 7-31
7.3-1 Option 1 7-33
7.3-2 Option 2 7-35
7.3-3 Option 3 7-37
7.3-4 Option 4 7-39
7.3-5 Option 5 7-41
7.3-6 Typical Parking Lot Layout 7-43
7.4-1 Trails and Public Access Options 7-45
7.5-1 Theoretical Inundation due to Lake Level with Swale 1 Excavated 7-47
7.5-2 Theoretical Inundation due to Lake Level with Swale 1 Excavated 7-48
7.6-1 Sewer Pipe Realignment Alternatives 7-49
7.6-2 Sewer Pipe Longitudinal Section 7-50

8-1 Scenario 1 8-9
8-2 Scenario 1: Details 8-11
8-3 Scenario 2 8-13
8-4 Scenario 2: Details 8-15
8-5 Scenario 3 8-17
8-6 Scenario 3: Details 8-19

TABLE OF CONTENTS (CONTINUED)

APPENDICES

A Images from the Geomorphic Reconnaissance of the Taylor Creek Watershed
B Images from the Geomorphic Reconnaissance of the Tallac and Spring Creek Watershed
C Taylor Creek Longitudinal Profile near SR 89 Bridge
D Tallac Creek Longitudinal Profile near SR 89
E Plant Species List
F Wildlife Inventory and Monitoring in the Lake Tahoe Basin, California: Pre-Restoration
G Fecal Coliform Levels at Tallac Creek, Baldwin Grazing Allotment
H Washoe Sources and Documentation