




Google earth





Google earth

feet
meters



COLLAPSED BANK AND SILT FENCE NOT WORKING
@ APPRX 35 02 50.71 N
83 07 14.84 W

STREAMER ROCK POOL
@ 35 02 54.50 N 83 07 12.98 W

Streamer Rock Pool

Google earth

Google earth

feet 100
meters 30



HUGE LOGJAM JUST UPSTREAM- OF CANE CREEK
IS UNBOATABLE AND MUST BE PORTAGED

@ APPRX

35 02 02.04 N

83 07 42.76 W

Huge Logjam above Cane Creek

OBSERVE HEAVY
SEDIMENT UPSTREAM

Google earth

Google earth

feet
meters

100

40



JUNE 6 2015 @ 12:56:46 PM
VIEW DOWNSTREAM AT LWD LOGJAM
@ APPRX 35 03 20.22 N 83 07 05.79 W
PRECLUDING BOATERS
FROM FLOATING THIS SECTION WITHOUT GETTING UP INTO
RHODODENDRON OR CLIMBING OVER LOGS

"FRONT LOGJAM"

A photograph of a river with a large logjam in the background. The river is in the foreground, with ripples on its surface. In the middle ground, a large pile of logs and branches is jammed across the river. The background is a dense forest with green trees and some pink blossoms on the right.

JUNE 6 2015 @ 1:14:19 PM

VIEW DOWNSTREAM AT LWD BLOCKING RIVER

@ APPRX 35 03 19.87 N 83 07 05.55 W



"A"

"E"

"F"

"REAR LOGJAM"

ROCK "LJ-1"

JUNE 29 2015 @ 2:45:18 PM
VIEW BACKDOWNSTREAM AT HUGE LOGJAM
@ 35 02 02 04 N 83 07 42.76 W



JUNE 29 2015 @ 2:44:25 PM

UPSTREAM VIEW OF HUGE SEDIMENT DEPOSIT


JUST ABOVE HUGE LOGJAM

@ 35 02 02 04 N 83 07 42.76 W



JUNE 29 2015 @ 8:35:39 AM

VIEW DOWN THE CHATTOOGA RIVER TRAIL



JUNE 29 2015 @ 8:35:57 AM

COLLAPSED BANK RIVER RIGHT & SILT FENCE

@ APPRX 35 02 50.71 N 83 07 14.84 W



COLLAPSED SILT FENCE

JUNE 29 2015 @ 8:36:41 AM

VIEW FROM TOP OF RIVER RIGHT BANK

SHOWING HOW BANK IS COLLAPSING WHERE
BEDFORM DIVERSITY HAS BEEN ELIMINATED AS CONSEQUENCE OF
EXCESSIVE SEDIMENT INPUT DURING THE TIME THAT BOATING HAS
BEEN PERMITTED



JUNE 29 2015 @ 8:36:50 AM

APPRX 35 02 50.71 N 83 07 14.84 W

COLLAPSED BANK
RIVER RIGHT &
SILT FENCE



JUNE 29 2015 @ 8:36:58 AM

APPRX 35 02 50.71 N 83 07 14.84 W



JUNE 29 2015 @ 8:39:43AM

@ APPRX

LOG "VZ"

