

**Appendix B**

**Site Photographs**

### MAGNOLIA MINE PHOTOGRAPHS



Photo 1      Date: 7/18/03      Top of upper waste pile sample location MAGN-14 at Magnolia Mine.  
Time: 1340



Photo 2      Date: 7/18/03      Sample location at lower waste pile – middle at Magnolia Mine (MAGN-16).  
Time: 1425



Photo 3      Date: 7/18/03      Closeup of sample MAGN-15 with stream in background.  
Time: 1500



Photo 4      Date: 7/18/03      Sample location at lower waste pile – southern end above Lucas Gulch  
Time: NA      (MAGN-17) at Magnolia Mine.



Photo 5      Date: 7/18/03      Adit drainage path at Magnolia.  
Time: NA



Photo 6      Date: 7/18/03      View of two ponds (Magnolia Mine).  
Time: NA



Photo 7      Date: 7/18/03      View of recent excavation (Magnolia Mine).  
Time: NA



Photo 8      Date: 7/18/03      View of recently excavated sediment from upper settling pond (Magnolia Mine).  
Time: NA



Photo 9

Date: 7/18/03  
Time: NA

View of adit on Lucas Gulch west of settling ponds, drainage into creek (Magnolia Mine).



Photo 10

Date: 7/18/03  
Time: NA

View of primary adit showing drainage into ponds (Magnolia Mine).



Photo 11 Date: 7/18/03 View of *Equisetum* (a few sedges on the side) showing red iron oxide  
Time: NA (Magnolia Mine).



Photo 12 Date: 7/18/03 Structure at Magnolia Mine.  
Time: NA



Photo 13

Date: 7/18/03  
Time: NA

Pool at MAGN-02 with small redband trout or westslope cutthroat trout (Magnolia Mine).

### AJAX MINE PHOTOGRAPHS



Photo 14      Date: 7/17/03      View of waste pile site (Ajax Mine).  
Time: NA



Photo 15      Date: 7/17/03      View of settling pond (Ajax Mine).  
Time: NA



Photo 16      Date: 7/18/03      Waste pile sample location (AJAX-10) at Ajax Mine.  
Time: 1248



Photo 17      Date: 7/18/03      Adit above waste pile at Ajax Mine.  
Time: 1250



Photo 18      Date: 7/17/03      View from adit at road showing waste pile and stream located immediately  
Time: 1030      behind wastepile (Ajax Mine).



Photo 19      Date: 7/17/03      View of settling pond - shows muddy nature of sediment (Ajax Mine).  
Time: 1030



Photo 20      Date: 7/17/03      South of settling pond showing seep that enters stream (Ajax Mine).  
Time: 1030



Photo 21      Date: 7/17/03      Closeup of seep (Ajax Mine).  
Time: 1030



Photo 22 Date: 7/17/03 Closer view of Lucas Gulch (Ajax Mine).  
Time: 1030



Photo 23 Date: 7/17/03 View of seep and sample location (Ajax Mine).  
Time: NA



Photo 24      Date: 7/17/03      Riffle looking upstream (AJAX-04).  
Time: NA

**GRANITE CREEK PHOTOGRAPHS (NEAR LUCAS GULCH CONFLUENCE)**



Photo 25

Date: 7/17/03 View of open nature of Granite Creek above Lucas Gulch entrance  
Time: NA



Photo 26

Date: 7/17/03 View upstream of pool site (GRAN-53).  
Time: NA