

FIGURE 1
BLUE LEDGE MINE SITE LOCATION, SURFACE DRAINAGES, FEATURES




FIGURE 2
 BLUE LEDGE MINE WASTE ROCK PILES ABOVE JOE CREEK




FIGURE 3
DISSOLVED COPPER-ZINC IN JOE CREEK SPIKE BELOW MINE




FIGURE 4
MACROINVERTEBRATES ABSENT BELOW MINE