



PHOTO 1
BROWN ALGAE MAT IS ONLY LIVING ORGANISM IN JOE CREEK BELOW MINE



PHOTO 2
TYPICAL SURFACE EROSION OF WASTE ROCK PILES



PHOTO 3
ACID MINE DRAINAGE ENTERING JOE CREEK



PHOTO 4
STEEP WASTE ROCK PILES BETWEEN ROCK CLIFFS



PHOTO 5
TYPICAL WASTE ROCK AND SULFIDES OVERLAYING NATIVE SOIL