Preassessment Screen
For the Blue Ledge Mine Site

Prepared for Consideration and Review by:

Rogue River/Siskiyou National Forests
333 West 8th Street
Medford, OR 97501

Prepared by:

Environment International Ltd.
5505 34th Avenue NE
Seattle, WA 98105

Under Contract # 53-0M00-2-29

October 28, 2002

Page Intentionally Left Blank

TABLE OF CONTENTS

EXECUTIVE SUMMARY 1

1.0 INTRODUCTION 3

2.0 THE BLUE LEDGE MINE AND ITS ENVIRONS 5
- 2.1 Location and Site Characteristics 5
- 2.2 Geology 7
- 2.3 Climate and Hydrology 8
- 2.4 Natural Resources of the Rogue River National Forest near the Mine 9

3.0 SITE HISTORY AND INFORMATION REGARDING THE RELEASE OF HAZARDOUS SUBSTANCES AT THE BLUE LEDGE MINE SITE 10
- 3.1 History, Uses and Relevant Operations at the Site 10
- 3.2 Information Regarding the Type, Quantity, and Frequency of Releases of Hazardous Substances 12
  - 3.2.1 Acid Mine and Rock Drainage – A Source of Hazardous Substances 12
  - 3.2.2 Sources and Nature of Releases of AMD 12
  - 3.2.3 Duration and Frequency of Releases of Hazardous Substances 19

4.0 PRELIMINARY IDENTIFICATION OF RESOURCES POTENTIALLY AT RISK 20
- 4.1 Preliminary Identification of Exposure Pathways and Exposed Areas 20
  - 4.1.1 Surface Water and Particulate Movement 20
  - 4.1.2 Groundwater 22
  - 4.1.3 Food Chain Pathways 22
- 4.2 Exposed Areas 23
- 4.3 Affected and Potentially Affected Resources 23
  - 4.3.1 Surface Water Resources 23
  - 4.3.2 Groundwater Resources 26
  - 4.3.3 Biologic Resources 26

5.0 POTENTIALLY RESPONSIBLE PARTIES 34

6.0 DAMAGES EXCLUDED FROM LIABILITY 37
- 6.1 Irreversible and Irretrievable Commitment of Resources Identified in an Environmental Impact Statement 37
- 6.2 Releases and Damages Occurring Wholly Before 1980 37
- 6.3 Damages Resulting from the Application of a Pesticide Product or Release of Recycled Oil 38
- 6.4 Federally Permitted Release 38
- 6.5 Exclusions from Liability under the Clean Water Act Section 311 38

7.0 PRELIMINARY DETERMINATION REGARDING PREASSESSMENT SCREEN CRITERIA 39

8.0 CONCLUSION 41

REFERENCES 42

MAPS, PHOTOS, CHARTS, AND TABLES

Maps

1. **Site Location** **6**
2. **Water Samples, 2000 & 2001** **16**
3. **Macroinvertebrate Survey Locations** **28**
4. **Presence/Absence of Fish** **32**

Photos

1. **Blue Ledge Mine and Waste Area Seen From FS Road 1060** **5**
2. **Blue Ledge Mine Site, circa 1913** 7
3. **Blue Ledge Mine Building, circa 1915** **10**
4. **Blue Ledge Mine Building, circa 1915** **11**
5. **Fines on the steep slopes above FS Road 1060** **13**

Charts

1. **Minimum, Mean, and Maximum Monthly Flows at Elliott Creek at Mouth** **8**
2. **Metal Concentrations, Joe Creek, 4/01** **17**
3. **Cadmium Concentrations, Joe Creek, 4/01** **17**
4. **Metal Concentrations in Elliott Creek, before and after confluence with Joe Creek, 4/01** **18**
5. **Macroinvertebrates, Sept. 2000 (Dry Season)** **29**
6. **Macroinvertebrates, May 2001 (Wet Season)** **29**
7. **Amphibian Observations in Joe Creek, 2000** **30**
8. **Rainbow Trout Observations in Joe and Elliott Creeks at Locations Downstream of Joe Creek** **31**

Tables

1. **Exceedances of Primary and Secondary Drinking Water Standards** **19**
2. **Aquatic Life Criteria as a Function of Hardness** **24**
3. **Exceedances of Aquatic Life Criteria for Cadmium** **24**
4. **Exceedances of Aquatic Life Criteria for Copper** **25**
5. **Exceedances of Aquatic Life Criteria for Zinc** **25**
6. **History of Blue Ledge Mine Ownership and Operations** **35**