

|   |                         |  |                                     |
|---|-------------------------|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA              |                         | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
| <b>Photo No.</b><br><b>69</b>                                 | <b>Date:</b><br>4-28-11 |  |                                     |
| <b>Direction Photo Taken:</b><br><br>West                     |                         |  |                                     |
| <b>Description:</b><br><br>Ball mill debris at mill building. |                         |  |                                     |

|  |                         |  |
|--|-------------------------|--|
| <b>Photo No.</b><br><b>70</b>                                      | <b>Date:</b><br>4-28-11 |  |
| <b>Direction Photo Taken:</b><br><br>North                         |                         |  |
| <b>Description:</b><br><br>Concrete pad to south of mill building. |                         |  |

|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|                               |                         |
|-------------------------------|-------------------------|
| <b>Photo No.</b><br><b>71</b> | <b>Date:</b><br>4-28-11 |
|-------------------------------|-------------------------|

**Direction Photo Taken:**  
  
Northeast

**Description:**  
  
Concrete pad to south of mill building, ball mill/debris pictured left.



|                               |                         |
|-------------------------------|-------------------------|
| <b>Photo No.</b><br><b>72</b> | <b>Date:</b><br>4-28-11 |
|-------------------------------|-------------------------|

**Direction Photo Taken:**  
  
East

**Description:**  
  
Ball/mill debris pictured at mill building.



|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|                               |                         |
|-------------------------------|-------------------------|
| <b>Photo No.</b><br><b>73</b> | <b>Date:</b><br>4-28-11 |
|-------------------------------|-------------------------|

|   |
|---|
| <b>Direction Photo Taken:</b><br><br>East |
|---|

|   |
|---|
| <b>Description:</b><br><br>Upper level and ramp of mill building. |
|---|



|                               |                         |
|-------------------------------|-------------------------|
| <b>Photo No.</b><br><b>74</b> | <b>Date:</b><br>4-28-11 |
|-------------------------------|-------------------------|

|  |
|--|
| <b>Direction Photo Taken:</b><br><br>Northwest |
|--|

|  |
|--|
| <b>Description:</b><br><br>Fence transition shown from 6-foot chain link to 4-strand barbed-wire on west perimeter, just south of access gate (See Figure E1). |
|--|



|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|                               |                         |
|-------------------------------|-------------------------|
| <b>Photo No.</b><br><b>75</b> | <b>Date:</b><br>4-28-11 |
|-------------------------------|-------------------------|

**Direction Photo Taken:**  
  
Southwest

**Description:**  
  
View of west fence; 4-strand barbed-wire fence (See Figure E1).



|                               |                         |
|-------------------------------|-------------------------|
| <b>Photo No.</b><br><b>76</b> | <b>Date:</b><br>4-28-11 |
|-------------------------------|-------------------------|

**Direction Photo Taken:**  
  
West/Northwest

**Description:**  
  
Fence transition shown from 6-foot chain link to 4-strand barbed-wire on west perimeter, just south of access gate (See Figure E1).



|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|                               |                         |
|-------------------------------|-------------------------|
| <b>Photo No.</b><br><b>77</b> | <b>Date:</b><br>4-28-11 |
|-------------------------------|-------------------------|

**Direction Photo Taken:**  
  
West

**Description:**  
  
Box culvert on west side of site, ~6-foot x 5 foot opening (See Figure E1).



|                               |                         |
|-------------------------------|-------------------------|
| <b>Photo No.</b><br><b>78</b> | <b>Date:</b><br>4-28-11 |
|-------------------------------|-------------------------|

**Direction Photo Taken:**  
  
North

**Description:**  
  
West fence line on hillside, looking downhill; 4-strand barbed-wire fence (See Figure E1).



|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|   |                         |
|---|-------------------------|
| <b>Photo No.</b><br><b>79</b>             | <b>Date:</b><br>4-28-11 |
| <b>Direction Photo Taken:</b><br><br>West |                         |

**Description:**  
  
USFS sign has fallen off fence (See Figure E1).



|   |                         |
|---|-------------------------|
| <b>Photo No.</b><br><b>80</b>             | <b>Date:</b><br>4-28-11 |
| <b>Direction Photo Taken:</b><br><br>West |                         |

**Description:**  
  
Large gaps under fence indicate fence has been disturbed to permit site access by unauthorized personnel (See Figure E1).



|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|                               |                         |
|-------------------------------|-------------------------|
| <b>Photo No.</b><br><b>81</b> | <b>Date:</b><br>4-28-11 |
|-------------------------------|-------------------------|

|  |
|--|
| <b>Direction Photo Taken:</b><br><br>South |
|--|

|   |
|---|
| <b>Description:</b><br><br>Southwest corner of fence post, fence continues across drainage (See Figure E1). |
|---|



|                               |                         |
|-------------------------------|-------------------------|
| <b>Photo No.</b><br><b>82</b> | <b>Date:</b><br>4-28-11 |
|-------------------------------|-------------------------|

|   |
|---|
| <b>Direction Photo Taken:</b><br><br>West |
|---|

|   |
|---|
| <b>Description:</b><br><br>Site fence crosses drainage on the south side of the site (See Figure E1). |
|---|



|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|                               |                         |
|-------------------------------|-------------------------|
| <b>Photo No.</b><br><b>83</b> | <b>Date:</b><br>4-28-11 |
|-------------------------------|-------------------------|

**Direction Photo Taken:**  
  
South

**Description:**  
  
Log placed on top of area where site fence is down (See Figure E1).



|                               |                         |
|-------------------------------|-------------------------|
| <b>Photo No.</b><br><b>84</b> | <b>Date:</b><br>4-28-11 |
|-------------------------------|-------------------------|

**Direction Photo Taken:**  
  
South

**Description:**  
  
Site fence is down; fence strands twisted together (See Figure E1).



|   |                         |  |                                     |
|---|-------------------------|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA            |                         | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
| <b>Photo No.</b><br><b>85</b>                               | <b>Date:</b><br>4-28-11 |  |                                     |
| <b>Direction Photo Taken:</b><br><br>West                   |                         |  |                                     |
| <b>Description:</b><br><br>Site fence down (See Figure E1). |                         |  |                                     |

|   |                         |  |  |
|---|-------------------------|--|--|
| <b>Photo No.</b><br><b>86</b>   | <b>Date:</b><br>4-28-11 |  |  |
| <b>Direction Photo Taken:</b><br><br>South  |                         |  |  |
| <b>Description:</b><br><br>Fence transitions from 4-strand barbed-wire to 6-foot chain link with no top rail (See Figure E1). |                         |  |  |

|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|                               |                         |
|-------------------------------|-------------------------|
| <b>Photo No.</b><br><b>87</b> | <b>Date:</b><br>4-28-11 |
|-------------------------------|-------------------------|

**Direction Photo Taken:**  
  
Southeast

**Description:**  
  
Fence spans drainage, and corrugated pipe (culvert is useless). Drainage opening is ~6 feet x 3 feet (See Figure E1).



|                               |                         |
|-------------------------------|-------------------------|
| <b>Photo No.</b><br><b>88</b> | <b>Date:</b><br>4-28-11 |
|-------------------------------|-------------------------|

**Direction Photo Taken:**  
  
Northwest

**Description:**  
  
Debris pile on southeast corner of site.



|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|                               |                         |
|-------------------------------|-------------------------|
| <b>Photo No.</b><br><b>89</b> | <b>Date:</b><br>4-28-11 |
|-------------------------------|-------------------------|

**Direction Photo Taken:**  
  
Southeast

**Description:**  
  
Fence transitions from steel tube posts to T-posts ~40 linear feet (See Figure E1).



|                               |                         |
|-------------------------------|-------------------------|
| <b>Photo No.</b><br><b>90</b> | <b>Date:</b><br>4-28-11 |
|-------------------------------|-------------------------|

**Direction Photo Taken:**  
  
Northeast

**Description:**  
  
Fence transitions from steel tube posts to T-posts ~40 linear feet (See Figure E1).



|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|                               |                         |
|-------------------------------|-------------------------|
| <b>Photo No.</b><br><b>91</b> | <b>Date:</b><br>4-28-11 |
|-------------------------------|-------------------------|

**Direction Photo Taken:**  
  
East

**Description:**  
  
Fence is in disrepair; view of an ~10-foot unsecured section that is in need of repair (See Figure E1).



|                               |                         |
|-------------------------------|-------------------------|
| <b>Photo No.</b><br><b>92</b> | <b>Date:</b><br>4-28-11 |
|-------------------------------|-------------------------|

**Direction Photo Taken:**  
  
East

**Description:**  
  
Fence spans what likely used to be drainage; corrugated pipe is useless. Fence needs extension or hole filled in (See Figure E1).



|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|                               |                         |
|-------------------------------|-------------------------|
| <b>Photo No.</b><br><b>93</b> | <b>Date:</b><br>4-28-11 |
|-------------------------------|-------------------------|

**Direction Photo Taken:**  
  
East

**Description:**  
  
Gate for El Paso gas access (See Figure E1).



|                               |                         |
|-------------------------------|-------------------------|
| <b>Photo No.</b><br><b>94</b> | <b>Date:</b><br>4-28-11 |
|-------------------------------|-------------------------|

**Direction Photo Taken:**  
  
East

**Description:**  
  
Fence spans concrete spillway on northeast corner of site, ~50 linear feet is in need of repair (See Figure E1).



|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|                               |                         |
|-------------------------------|-------------------------|
| <b>Photo No.</b><br><b>95</b> | <b>Date:</b><br>4-28-11 |
|-------------------------------|-------------------------|

|   |
|---|
| <b>Direction Photo Taken:</b><br><br>East |
|---|

**Description:**  
  
Fence spans concrete spillway on northeast corner of site, ~50 linear feet is in need of repair (See Figure E1).



|                               |                         |
|-------------------------------|-------------------------|
| <b>Photo No.</b><br><b>96</b> | <b>Date:</b><br>4-28-11 |
|-------------------------------|-------------------------|

|   |
|---|
| <b>Direction Photo Taken:</b><br><br>East |
|---|

**Description:**  
  
Fence spans concrete spillway on northeast corner of site, ~50 linear feet is in need of repair (See Figure E1).



|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|                               |                         |
|-------------------------------|-------------------------|
| <b>Photo No.</b><br><b>97</b> | <b>Date:</b><br>4-28-11 |
|-------------------------------|-------------------------|

**Direction Photo Taken:**  
  
Northeast

**Description:**  
  
Northeast corner of fence needs new corner post and ~15 linear feet is in need of repairs (See Figure E1).



|                               |                         |
|-------------------------------|-------------------------|
| <b>Photo No.</b><br><b>98</b> | <b>Date:</b><br>4-28-11 |
|-------------------------------|-------------------------|

**Direction Photo Taken:**  
  
North

**Description:**  
  
Fence spans drainage on northern site perimeter, fence extension needed into drainage and ~25 linear feet of repairs needed (See Figure E1).



|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|                               |                         |
|-------------------------------|-------------------------|
| <b>Photo No.</b><br><b>99</b> | <b>Date:</b><br>4-28-11 |
|-------------------------------|-------------------------|

**Direction Photo Taken:**  
  
Southwest

**Description:**  
  
Picture of waste pile A: not sampled (See Figure 8 for location on Site).



|                                |                         |
|--------------------------------|-------------------------|
| <b>Photo No.</b><br><b>100</b> | <b>Date:</b><br>4-28-11 |
|--------------------------------|-------------------------|

**Direction Photo Taken:**  
  
Southwest

**Description:**  
  
Picture of waste pile B; PA/SI sample SM-A4-WS-5 (See Figure 8 for location on Site).



|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|  |                         |  |
|--|-------------------------|--|
| <b>Photo No.</b><br><b>101</b>   | <b>Date:</b><br>4-28-11 |  |
| <b>Direction Photo Taken:</b><br><br>South   |                         |  |
| <b>Description:</b><br><br>Picture of waste pile C; EE/CA sample A4-WS4E (asbestos <1%) (See Figure 8 for location on Site). |                         |  |

|   |                         |  |
|---|-------------------------|--|
| <b>Photo No.</b><br><b>102</b>  | <b>Date:</b><br>4-28-11 |  |
| <b>Direction Photo Taken:</b><br><br>Southeast  |                         |  |
| <b>Description:</b><br><br>Picture of waste pile C (See Figure 8 for location on Site). |                         |  |

|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|                                |                         |
|--------------------------------|-------------------------|
| <b>Photo No.</b><br><b>103</b> | <b>Date:</b><br>4-28-11 |
|--------------------------------|-------------------------|

**Direction Photo Taken:**  
  
East

**Description:**  
  
Picture of waste pile E; EE/CA A4-WS3E (See Figure 8 for location on Site).



|                                |                         |
|--------------------------------|-------------------------|
| <b>Photo No.</b><br><b>104</b> | <b>Date:</b><br>4-28-11 |
|--------------------------------|-------------------------|

**Direction Photo Taken:**  
  
Southeast

**Description:**  
  
Picture of waste pile F; not sampled (See Figure 8 for location on Site).



|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|   |                         |  |
|---|-------------------------|--|
| <b>Photo No.</b><br><b>105</b>  | <b>Date:</b><br>4-28-11 |  |
| <b>Direction Photo Taken:</b><br><br>North  |                         |  |
| <b>Description:</b><br><br>Picture of waste pile G;<br>PA/SI SM-A4-WS-2<br>(arsenic 64mg/kg) (See<br>Figure 8 for location on<br>Site). |                         |  |

|  |                         |  |
|--|-------------------------|--|
| <b>Photo No.</b><br><b>106</b>   | <b>Date:</b><br>4-28-11 |  |
| <b>Direction Photo Taken:</b><br><br>Northeast   |                         |  |
| <b>Description:</b><br><br>Picture of waste pile H;<br>PA/SI SM-A2-WS-11<br>(arsenic 73mg/kg) (See<br>Figure 8 for location on<br>Site). |                         |  |

|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|                                |                         |
|--------------------------------|-------------------------|
| <b>Photo No.</b><br><b>107</b> | <b>Date:</b><br>4-28-11 |
|--------------------------------|-------------------------|

**Direction Photo Taken:**  
  
West Southwest

**Description:**  
  
Picture of waste pile I; not sampled (See Figure 8 for location on Site).



|                                |                         |
|--------------------------------|-------------------------|
| <b>Photo No.</b><br><b>108</b> | <b>Date:</b><br>4-28-11 |
|--------------------------------|-------------------------|

**Direction Photo Taken:**  
  
South

**Description:**  
  
Picture of waste pile J; PA/SI SM-A4-WS-1 (arsenic 12mg/kg) (See Figure 8 for location on Site).



|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|                                |                         |
|--------------------------------|-------------------------|
| <b>Photo No.</b><br><b>109</b> | <b>Date:</b><br>4-28-11 |
|--------------------------------|-------------------------|

**Direction Photo Taken:**  
  
East

**Description:**  
  
Picture of waste pile K; not sampled (See Figure 8 for location on Site).



|                                |                         |
|--------------------------------|-------------------------|
| <b>Photo No.</b><br><b>110</b> | <b>Date:</b><br>4-28-11 |
|--------------------------------|-------------------------|

**Direction Photo Taken:**  
  
East

**Description:**  
  
Picture of waste pile L EE/CA A4-WS1E (See Figure 8 for location on Site).



|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|                                |                         |
|--------------------------------|-------------------------|
| <b>Photo No.</b><br><b>111</b> | <b>Date:</b><br>4-28-11 |
|--------------------------------|-------------------------|

**Direction Photo Taken:**  
  
West

**Description:**  
  
Picture of waste pile M; PA/SI SM-A3-WS-6 (See Figure 8 for location on Site).



|                                |                         |
|--------------------------------|-------------------------|
| <b>Photo No.</b><br><b>112</b> | <b>Date:</b><br>4-28-11 |
|--------------------------------|-------------------------|

**Direction Photo Taken:**  
  
North

**Description:**  
  
Picture of waste pile N; not (See Figure 8 for location on Site).



|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|   |                         |  |
|---|-------------------------|--|
| <b>Photo No.</b><br><b>113</b>  | <b>Date:</b><br>4-28-11 |  |
| <b>Direction Photo Taken:</b><br><br>Southeast  |                         |  |
| <b>Description:</b><br><br>Picture of east half of waste pile O; PA/SI SM-A2-WS-8 (asbestos <1%) (See Figure 8 for location on Site). |                         |  |

|  |                         |  |
|--|-------------------------|--|
| <b>Photo No.</b><br><b>114</b>   | <b>Date:</b><br>4-28-11 |  |
| <b>Direction Photo Taken:</b><br><br>Southwest   |                         |  |
| <b>Description:</b><br><br>Picture of west half of waste pile O (See Figure 8 for location on Site). |                         |  |

|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|  |                         |
|--|-------------------------|
| <b>Photo No.</b><br><b>115</b>   | <b>Date:</b><br>4-28-11 |
| <b>Direction Photo Taken:</b><br><br>Northwest   |                         |
| <b>Description:</b><br><br>Picture of waste pile P; not sampled (See Figure 8 for location on Site). |                         |



|  |                         |
|--|-------------------------|
| <b>Photo No.</b><br><b>116</b>   | <b>Date:</b><br>4-28-11 |
| <b>Direction Photo Taken:</b><br><br>West  |                         |
| <b>Description:</b><br><br>Picture of waste pile Q. EE/CA A2-WS4E (arsenic 18mg/kg) (See Figure 8 for location on Site). |                         |



|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|                                |                         |
|--------------------------------|-------------------------|
| <b>Photo No.</b><br><b>117</b> | <b>Date:</b><br>4-28-11 |
|--------------------------------|-------------------------|

**Direction Photo Taken:**  
  
North

**Description:**  
  
Picture of waste pile R;  
not sampled (See Figure 8  
for location on Site).



|                                |                         |
|--------------------------------|-------------------------|
| <b>Photo No.</b><br><b>118</b> | <b>Date:</b><br>4-28-11 |
|--------------------------------|-------------------------|

**Direction Photo Taken:**  
  
South

**Description:**  
  
Picture of waste pile S;  
not sampled (See Figure 8  
for location on Site).



|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|  |                         |  |
|--|-------------------------|--|
| <b>Photo No.</b><br><b>119</b>   | <b>Date:</b><br>4-28-11 |  |
| <b>Direction Photo Taken:</b><br><br>East  |                         |  |
| <b>Description:</b><br><br>Picture of waste pile T; not sampled (See Figure 8 for location on Site). |                         |  |

|  |                         |  |
|--|-------------------------|--|
| <b>Photo No.</b><br><b>120</b>   | <b>Date:</b><br>4-28-11 |  |
| <b>Direction Photo Taken:</b><br><br>West  |                         |  |
| <b>Description:</b><br><br>Picture of waste pile U; PA/SI SM-A2-WS-3 (arsenic 23 mg/kg) (See Figure 8 for location on Site). |                         |  |

|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|  |                         |  |
|--|-------------------------|--|
| <b>Photo No.</b><br><b>121</b>   | <b>Date:</b><br>4-28-11 |  |
| <b>Direction Photo Taken:</b><br><br>North   |                         |  |
| <b>Description:</b><br><br>Picture of waste pile V;<br>EE/CA sample A2-WS3E<br>(arsenic 40 mg/kg) (See<br>Figure 8 for location on<br>Site). |                         |  |

|  |                         |  |
|--|-------------------------|--|
| <b>Photo No.</b><br><b>122</b>   | <b>Date:</b><br>4-28-11 |  |
| <b>Direction Photo Taken:</b><br><br>West  |                         |  |
| <b>Description:</b><br><br>Picture of waste pile W;<br>EE/CA sample A2-WS1E<br>(arsenic 24 mg/kg) (See<br>Figure 8 for location on<br>Site). |                         |  |

|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|                                |                         |
|--------------------------------|-------------------------|
| <b>Photo No.</b><br><b>123</b> | <b>Date:</b><br>4-28-11 |
|--------------------------------|-------------------------|

**Direction Photo Taken:**  
  
East

**Description:**  
  
Picture of waste pile X; EE/CA A2-WS2E (arsenic 20 mg/kg) (See Figure 8 for location on Site).



|                                |                         |
|--------------------------------|-------------------------|
| <b>Photo No.</b><br><b>124</b> | <b>Date:</b><br>4-28-11 |
|--------------------------------|-------------------------|

**Direction Photo Taken:**  
  
Northeast

**Description:**  
  
Picture of waste pile X; (See Figure 8 for location on Site).



|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|                                |                         |
|--------------------------------|-------------------------|
| <b>Photo No.</b><br><b>125</b> | <b>Date:</b><br>4-28-11 |
|--------------------------------|-------------------------|

**Direction Photo Taken:**  
  
Northeast

**Description:**  
  
Picture of waste pile Y; PA/SI SM-A2-WS-4 (arsenic 29 mg/kg) (See Figure 8 for location on Site).



|                                |                         |
|--------------------------------|-------------------------|
| <b>Photo No.</b><br><b>126</b> | <b>Date:</b><br>4-28-11 |
|--------------------------------|-------------------------|

**Direction Photo Taken:**  
  
Northwest

**Description:**  
  
Picture of waste pile Y; (See Figure 8 for location on Site).



|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|                                |                         |
|--------------------------------|-------------------------|
| <b>Photo No.</b><br><b>127</b> | <b>Date:</b><br>4-28-11 |
|--------------------------------|-------------------------|

**Direction Photo Taken:**  
  
West

**Description:**  
  
Picture of waste pile Y;  
(See Figure 8 for location on Site).



|                                |                         |
|--------------------------------|-------------------------|
| <b>Photo No.</b><br><b>128</b> | <b>Date:</b><br>4-28-11 |
|--------------------------------|-------------------------|

**Direction Photo Taken:**  
  
Northwest

**Description:**  
  
Picture of waste pile Z;  
PA/SI SM-A2-WS-1  
(arsenic 49 mg/kg, lead 1,500 mg/kg) (See Figure 8 for location on Site).



|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|                                |                         |
|--------------------------------|-------------------------|
| <b>Photo No.</b><br><b>129</b> | <b>Date:</b><br>4-28-11 |
|--------------------------------|-------------------------|

**Direction Photo Taken:**  
  
East

**Description:**  
  
Picture of waste pile AA; PA/SI SM A2-WS-2 (arsenic 28 mg/kg) (See Figure 8 for location on Site).



|                                |                         |
|--------------------------------|-------------------------|
| <b>Photo No.</b><br><b>130</b> | <b>Date:</b><br>4-28-11 |
|--------------------------------|-------------------------|

**Direction Photo Taken:**  
  
Northwest

**Description:**  
  
Picture of waste pile BB, not sampled (See Figure 8 for location on Site).



|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|                                |                         |
|--------------------------------|-------------------------|
| <b>Photo No.</b><br><b>131</b> | <b>Date:</b><br>4-28-11 |
|--------------------------------|-------------------------|

**Direction Photo Taken:**  
  
West

**Description:**  
  
Picture of waste pile CC; EE/CA A1-WS1E (no exceedances) (See Figure 8 for location on Site).



|                                |                         |
|--------------------------------|-------------------------|
| <b>Photo No.</b><br><b>132</b> | <b>Date:</b><br>4-28-11 |
|--------------------------------|-------------------------|

**Direction Photo Taken:**  
  
East

**Description:**  
  
Picture of waste pile DD; PA/SI A1-WS-9 (arsenic 28 mg/kg, copper 58,000 mg/kg, lead 1,800 mg/kg) (See Figure 8 for location on Site).



|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|                                |                         |
|--------------------------------|-------------------------|
| <b>Photo No.</b><br><b>133</b> | <b>Date:</b><br>4-28-11 |
|--------------------------------|-------------------------|

**Direction Photo Taken:**  
  
South

**Description:**  
  
Picture of waste pile EE; PA/SI SM-A1-3 (arsenic 56 mg/kg, chromium 84 mg/kg, lead 1,800 mg/kg) (See Figure 8 for location on Site).



|                                |                         |
|--------------------------------|-------------------------|
| <b>Photo No.</b><br><b>134</b> | <b>Date:</b><br>4-28-11 |
|--------------------------------|-------------------------|

**Direction Photo Taken:**  
  
Northwest

**Description:**  
  
Picture of waste pile FF (See Figure 8 for location on Site).



|  |  |                                     |
|--|--|-------------------------------------|
| <b>Project Name:</b><br>Sunchief Mill Site EE/CA | <b>Site Location:</b><br>Tonto National Forest, Gila County, Arizona | <b>Project No.</b><br>12238.041.002 |
|--|--|-------------------------------------|

|   |                         |  |
|---|-------------------------|--|
| <b>Photo No.</b><br><b>135</b>  | <b>Date:</b><br>4-28-11 |  |
| <b>Direction Photo Taken:</b><br><br>East   |                         |  |
| <b>Description:</b><br><br>Picture of waste pile JJ; not sampled (See Figure 8 for location on Site). |                         |  |

|  |                         |  |
|--|-------------------------|--|
| <b>Photo No.</b><br><b>136</b>   | <b>Date:</b><br>4-28-11 |  |
| <b>Direction Photo Taken:</b><br><br>North   |                         |  |
| <b>Description:</b><br><br>Weston personnel standing in center of large potential on-site repository (large pond). |                         |  |