Entrance and Highway Frontage

Typical Grounds

Classroom Building

Bunk House

Mess Hall Views

Bunk House

One of Two Restroom/Shower Buildings

Bunk House

Sheet Shack

Building Cluster with Radio Tower

Contrasting Bunk House Setting

Shooting Range Shelter with Storage Room

Former Target Location – Note Overgrown Mound

Classroom Interior

Bunk House Interior with Closet

Second Bunk House Interior with Closet

Mess Hall Interior

Utility Building Interior

Restroom/Shower Building Interior

Vandalized Copper Plumbing and Wiring at a Restroom/Shower Building – Interior and Exterior

Sheet Shack Interior – Note Ceiling damage from fallen tree

Mess Hall Vandalism damage - Electrical Service

Ceiling Damage from Roof Leakage (Roof Repaired) and Raised Hearth Stone Fireplace in Mess Hall Addition

Deferred Roof and Ceiling Maintenance

Mess Hall Equipment and Walk-In Refrigeration Unit to the left Background

Water Distribution Control Valves

Utility Distribution Systems – All Subterranean Lines

Sewage Septic System Mound in the Distance Beyond the Recreation Area