Appendix D

Blackwood Post Construction Photos

2009, 2011

(includes 2 photos from 2012 at PP7A)

PP 1A Panorama 07/13/2009. Post Construction

PP1A Panorama 9/8/11. Post Construction

.

PP 2A 11/02/2009. Post Construction

PP2A 9/8/11. Post Construction

PP 2A Panorama 07/13/2009. Post Construction.

PP 2A Panorama 9/1/2011. Post Construccction

PP 5B Panorama 07/13/2009. Post Construction.

PP5B Panorama 9/1/11. Post Construction

PP 7 Panorama 11/09/2009.

PP7A Panorama 9/1/11.

See insets next page

PP7A 9/1/11 (inset 1)

PP7A July 2012

PP7A July 2012 (inset 2)

PP 9A Panorama 10/27/2009.

PP9A Panorama 9/13/11

See inset next page

PP 15B Panorama 11/09/2009

PP15B Panorama 9/1/2011

PP 17A Panorama 11/09/2009 Post Construction.

PP17A Panorama 9/1/11

PP 18A Panorama 11/09/2009 Post Construction.

PP17A Panorama 9/1/11

PP 23

10/12/2009

10/26/2009 (sediment deposit after storm event)

1 8/15/2011 (Sediment deposit gone)

PP27 10/12/2009

PP27 8/15/11

PP28 10/26/2009

PP28 8/15/11