


LEGEND

South Lambert Timber Sale

	Sale Area Boundary, BT1.1
	Payment Unit Boundary, BT1.1
	Payment Unit Number, BT1.1
CTM	Cut Tree Marked Prior to Advertisement, BT2.35, CT2.355#, CT6.412
	Existing Transportation System Road, BT5.1
	Keep Open, Existing Transportation System Road, BT5.12, BT5.4, CT5.12#
	Existing Transportation System Road, Unsuitable for hauling prior to completion of agreed reconstruction, BT5.12, CT5.12#
	Existing Road, Hauling Prohibited, BT5.12, CT5.12#
	Existing Road, Use Restricted BT5.12, CT5.12#
	Maintenance Drainage Structure, Purchaser Furnish/Install Culvert, CT5.31#, T-8340
	Purchaser Remove/Install Berm on System Road, CT5.31#, T-8620
	Specified Road Reconstruction, AT7, AT8, BT5.2, BT5.23, BT6.22, BT6.222, BT6.361, Schedule of Items
	Specified Road Construction, AT7, AT8, BT5.2, BT5.23, BT6.22, BT6.222, BT6.361, Schedule of Items
	Specified Drainage Structure, AT9, BT5.2, BT5.23, BT6.222, Schedule of Items
	Protection of Improvements, BT6.22, Existing Gate on FR 3110-R (Stambaugh Pit), CT5.31#, T-8620
	Protection of Improvements Not Owned by USFS, BT6.221 - WE Energy Powerline
	Protection of Improvements/Keep Trail Open, BT6.22 - Ge-Che Trail
	Streamcourse Protection, Block Marks Upper Limit, Arrow Indicates Flow Direction, BT6.5
WL	Wetland Protection, BT6.62, CT6.62#
SDZ	Slash Disposal, BT6.7, CT6.7#
SDZ(1)	Slash Disposal Zone, BT6.7, CT6.7#
SDZ(2)	Slash Disposal Zone, BT6.7, CT6.7#
SDZ(3)	Slash Disposal Zone, BT6.7, CT6.7#
	Other Ownership
	Safety- Purchaser to Provide and Maintain Traffic Control Signs, BT6.33
	Protect Known Survey Monuments, BT6.23
	Material Source, CT5.221#, T-8130 Spot Surface Replacement/Replenishment (Stambaugh Pit, T43N-R36W, Section 34)