



Appendix A

Blackwood Reach 6 Restoration Design Plans



Appendix A: Blackwood Reach 6 Restoration Design Plan – Upper Half



Appendix A: Blackwood Reach 6 Restoration Design Plan – Lower Half

Appendix B

Blackwood Restoration Monitoring Maps

Figure B1: Monitoring Locations for Blackwood Restored Reach Cross Sections and Photopoints







Figure B2: Monitoring Locations for Macroinvertebrates in Blackwood Restored and Reference Reaches






AppendixC

Blackwood Reach 6 Restoration Sinuosity Change

Appendix C: Blackwood Restored Reach 6 Sinuosity Changes







Appendix D

Blackwood Post Construction Photos


2009, 2011

(includes 2 photos from 2012 at PP7A)

PP 1A Panorama 07/13/2009. Post Construction



PP1A Panorama 9/8/11. Post Construction



PP 2A 11/02/2009. Post Construction




PP2A 9/8/11. Post Construction
PP 2A Panorama 07/13/2009. Post Construction.



PP 2A Panorama 9/1/2011. Post Construcction



PP 5B Panorama 07/13/2009. Post Construction.



PP5B Panorama 9/1/11. Post Construction



PP 7 Panorama 11/09/2009.



PP7A Panorama 9/1/11.



See insets next page

PP7A 9/1/11 (inset 1)



PP7A July 2012



PP7A July 2012 (inset 2)

PP 9A Panorama 10/27/2009.



PP9A Panorama 9/13/11



See inset next page



PP 15B Panorama 11/09/2009



PP15B Panorama 9/1/2011



PP 17A Panorama 11/09/2009 Post Construction.



PP17A Panorama 9/1/11



PP 18A Panorama 11/09/2009 Post Construction.



PP18A Panorama 9/1/11





PP 23 - 10/12/2009



PP 23 - 10/26/2009 (sediment deposit after storm event)



PP- 23 - 8/15/2011 (Sediment deposit gone)

PP27 10/12/2009



PP27 8/15/11



PP28 10/26/2009



PP28 8/15/11



Google Earth images illustrating sediment deposition processes in Blackwood Creek 2010 through 2012.





8/2012



Google earth

Imagery Date: 8/28/2012 1969 39°06'38.52" N 120°10'52.11" W elev 6328 ft

Eye alt 7219 ft

Appendix E

Blackwood Reach 6 Stream Condition Inventory Data and Figures

E1: Stream Condition Inventory Data

E2: Thalweg Survey Profiles

Appendix E1: Stream Condition Inventory Transect Data

W/D and Entrenchment measured at 8 cross sections/transects in 1996.1997, 2001, and at all fast water units in 2011.

Width Depth Ratios

SCI Reach				RR6	Restored Reach	RR4
1996	1997	2001	2011	2011	2011	2011
44.3	25.23	10.4	47.2	14.4	22.2	49.6
40.6	30.12	16.7	53.3	41.7	27.0	18.9
34.5	67.7	76.8	22.2	28.5	44.3	45.5
22.4	20.27	6.3	27	28.8	18.0	41.7
29.9	20.5	13.4	44.3	45.1	16.6	28.6
25.3	30.2	14.6	18	69.5	16.6	33.4
38.7	32.9	9.8	16.6	17.8	25.9	22.0
25.6	27.7	7	20.1			13.1
			25.9			34.6
						39.8
						32.8

32.2	28.9	11.9	25.9	28.8	22.2	33.4	Medians
-------------	-------------	-------------	-------------	-------------	-------------	-------------	---------

Entrenchment Ratios

SCI Reach				RR6	Restored Reach	RR4
1996	1997	2001	2011	2011	2011	2011
1	4.1	3.7	1.3	1.8	1.7	2.6
3	4	2	2.9	1.2	3.3	1.2
1.1	3.1	1.6	1.7	3.7	5.3	1.5
1.7	4.4	5.3	3.3	9.1	15.5	1.9
3	4.9	2	5.3	8.7	16.2	2
2.2	1.6	1.2	15.5	1.6	14.5	4
3.2	4.5	1.6	16.2	2.9	10.4	10.9
1.4	4.1	2	14.5			1
			10.4			3.8
						1.7
						2.2
2.0	4.1	2.0	5.3	2.9	10.4	2.0

Medians

Total Shade

SCI Reach				RR6	Restored Reach	RR4
1996	1997	2001	2011	2011	2011	2011

34	5	3	14	36	12	0
8	5	13	11	35	0	0
5	2	33	12	37	0	14
6	4	11	0	27	11	4
5	44	5	0	4	5	9
2	27	4	11	9	14	2
9	9	25	5	3	5	14
7	6	3	14			21
6	16	4	5			13
6	53	4				31
3.5	21	4				12
16.5	12	4				
10	7	7				
7	3	7				
18	3	3				
15	5	47				
1	11	29				
14	7	3				
19	9	2				
3	5	8				
16	10	10				
5	11	6				
5	19	2				
5	0	1				
9	5	2				
1	14	12				
6	12	3				
8	21	2				
4	24	26				
10	4	8				
16	13	6				
20	3	4				
30	5	3				
54	2	2				
51	3	4				
18	3	26				
46	2	27				
20	11	23				
9	6	36				
31	4	8				
18	13	13				
25	11	7				
15	7	6				
2	15	3				
4	15	3				
3	22	2				
1	8	2				
3	6	2				
3	7	4				
3	42	0				
1.3	11	9				
8	8	4	11	27	5	12

Medians

Measured along 50 evenly spaced transects in 1996, 1997, and 2001. Measured at all fast water units in 2011.

pieces of Large Wood in 2011

SCI Reach				RR6	Restored Reach	RR4
1996	1997	2001	2011	2011	2011	2011

See next page			2	3	1	1
			0	0	0	1
			0	1	2	0
			0	0	1	1
			1	0	0	0
			0	0	0	0
			2	0	0	0
			1		0	1
			0		0	0
			0		0	1
			0		0	0
			0		0	0
			0		0	0
			0		0	0
			0		1	0
			0			0
			0			1
			0			0
			1			0
						1
						4
Totals						
32	12	59	7	4	5	11

2011 large wood definition: $L = \text{Diameter} > 20 \text{ in } (.5\text{m})$ at a length of 35 ft. (10.6m) from the large end

SCI Large Wood Data 1996, 1997, and 2001

1996

Length Class(m)	0.4 to 0.8	0.8 to 1.6	>1.6
8 to 16	22	5	
16 to 32			
> 32	5		

Total = 32

1997

Length Class(m)	0.4 to 0.8	0.8 to 1.6	>1.6
8 to 16	5		
16 to 32	7		
> 32			

Total = 12


2001

Length Class(m)	0.4 to 0.8	0.8 to 1.6	>1.6
8 to 16	39		
16 to 32	20		
> 32			


Total - 59

Pre-2011 large wood definition: L = Diameter > .4.m , length $\geq$ 8m

E2: Blackwood Thalweg Profiles




2001 Restored Reach (Pre-Restoration) Thalweg Profile




2011 Restored Reach (Post Restoration) Thalweg Profile


(2001 measured by Swanson Hydrology, 2011 measured by LTBMU)




2001 Reference Reach 4 Thalweg Profile



2011 Reference Reach 4 Thalweg Profile



2001 Reference Reach 6 Thalweg Profile



2011 Reference Reach 6 Thalweg Profile




Appendix F

Blackwood Reach 6 Restoration Cross Sections


F1: Cross Section Graphs

F2: Scour and Fill Graphs


Appendix F.1 Blackwood Creek SCI Reach Cross Sections




Blackwood Creek XS-10






Blackwood Creek XS-20




Blackwood Creek XS-30




F2: Blackwood Cross Sections Scour and Fill



Blackwood XS 10



Blackwood XS 20



Blackwood XS 30

