Appendix B: 20 Mile Creek Restoration Project Photos

PHOTO 1. OLD RAILROAD GRADE AND REMNANT CULVERT AT 20 MILE CREEK



PHOTO 2. TAILWATER CONTROL AND BRAIDED CHANNEL BELOW OLD CROSSING

Appendix B: 20 Mile Creek Restoration Project Photos

PHOTO 3. BRAIDED, OVER-STEEPENED CHANNEL BELOW OLD CROSSING AT 20 MILE CREEK



PHOTO 4. LOWER END OF PLUNGE POOL, TAILWATER CONTROL AND BRAIDED CHANNEL

Appendix B: 20 Mile Creek Restoration Project Photos







5. Top Left: Upstream of Remnant Culvert

6. Top Right: Downstream Remnant Culvert

7. Lower Left: 20 Mile Creek below Culvert

8. Lower Right: 20 Mile Creek Below Culvert